























































	<p>ПЗ-01</p> <p> $F \text{ см}^2 = 6.540$ $Q \text{ кг.} = 1.772$ $D \text{ оп.мм} = 139.0$ $P \text{ н.мм} = 309.8$ $P \text{ вн.мм} = 337.8$ Гр. сл. = IV Точн. = Н </p>		<p>ПЗ-06</p> <p> $F \text{ см}^2 = 2.548$ $Q \text{ кг.} = 0.691$ $D \text{ оп.мм} = 53.5$ $P \text{ н.мм} = 235.0$ $P \text{ вн.мм} = 134.0$ Гр. сл. = V Точн. = П </p>
	<p>ПЗ-02</p> <p> $F \text{ см}^2 = 3.506$ $Q \text{ кг.} = 0.950$ $D \text{ оп.мм} = 67.0$ $P \text{ н.мм} = 243.0$ $P \text{ вн.мм} = 106.5$ Гр. сл. = V Точн. = Н </p>		<p>ПЗ-7</p> <p> $F \text{ см}^2 = 0.952$ $Q \text{ кг.} = 0.258$ $D \text{ оп.мм} = 32.0$ $P \text{ н.мм} = 120.5$ $P \text{ вн.мм} = 36.0$ Гр. сл. = 0соб. Точн. = П </p>
	<p>ПЗ-03</p> <p> $F \text{ см}^2 = 1.324$ $Q \text{ кг.} = 0.359$ $D \text{ оп.мм} = 31.8$ $P \text{ н.мм} = 112.2$ $P \text{ вн.мм} = 64.0$ Гр. сл. = VI Точн. = Н </p>		<p>ПЗ-08</p> <p> $F \text{ см}^2 = 4.200$ $Q \text{ кг.} = 1.138$ $D \text{ оп.мм} = 90.0$ $P \text{ н.мм} = 342.3$ $P \text{ вн.мм} = 114.4$ Гр. сл. = 0соб. Точн. = П </p>
	<p>ПЗ-04</p> <p> $F \text{ см}^2 = 3.060$ $Q \text{ кг.} = 0.829$ $D \text{ оп.мм} = 54.0$ $P \text{ н.мм} = 135.7$ $P \text{ вн.мм} = 120.8$ Гр. сл. = V Точн. = П </p>		
			<p>ПЗ-10</p> <p> $F \text{ см}^2 = 1.800$ $Q \text{ кг.} = 0.488$ $D \text{ оп.мм} = 50.0$ $P \text{ н.мм} = 165.0$ $P \text{ вн.мм} = 75.0$ Гр. сл. = VI Точн. = П </p>










	<p>ПЗ-11</p> <p> $F \text{ см}^2 = 2.335$ $Q \text{ кг.} = 0.633$ $D \text{ оп.мм} = 56.0$ $P \text{ н.мм} = 221.2$ $P \text{ вн.мм} = 132.0$ Гр. сл. = V Точн. = П </p>		<p>ПЗ-16</p> <p> $F \text{ см}^2 = 2.544$ $Q \text{ кг.} = 0.689$ $D \text{ оп.мм} = 42.4$ $P \text{ н.мм} = 182.3$ $P \text{ вн.мм} = 57.1$ Гр. сл. = V Точн. = П </p>
	<p>ПЗ-12</p> <p> $F \text{ см}^2 = 1.313$ $Q \text{ кг.} = 0.356$ $D \text{ оп.мм} = 32.0$ $P \text{ н.мм} = 132.0$ $P \text{ вн.мм} = 67.0$ Гр. сл. = V Точн. = П </p>		<p>ПЗ-17</p> <p> $F \text{ см}^2 = 2.695$ $Q \text{ кг.} = 0.730$ $D \text{ оп.мм} = 43.0$ $P \text{ н.мм} = 200.9$ $P \text{ вн.мм} = 57.1$ Гр. сл. = VI Точн. = П </p>
	<p>ПЗ-13</p> <p> $F \text{ см}^2 = 5.190$ $Q \text{ кг.} = 1.406$ $D \text{ оп.мм} = 84.1$ $P \text{ н.мм} = 321.6$ $P \text{ вн.мм} = 124.0$ Гр. сл. = VI Точн. = Н </p>		<p>ПЗ-18</p> <p> $F \text{ см}^2 = 3.014$ $Q \text{ кг.} = 0.817$ $D \text{ оп.мм} = 46.8$ $P \text{ н.мм} = 172.3$ $P \text{ вн.мм} = 129.1$ Гр. сл. = V Точн. = П </p>
	<p>ПЗ-15</p> <p> $F \text{ см}^2 = 1.927$ $Q \text{ кг.} = 0.522$ $D \text{ оп.мм} = 52.0$ $P \text{ н.мм} = 178.4$ $P \text{ вн.мм} = 78.6$ Гр. сл. = IV Точн. = П </p>		<p>ПЗ-19</p> <p> $F \text{ см}^2 = 2.926$ $Q \text{ кг.} = 0.793$ $D \text{ оп.мм} = 46.1$ $P \text{ н.мм} = 217.5$ $P \text{ вн.мм} = 57.4$ Гр. сл. = VI Точн. = П </p>
	<p>ПЗ-20</p> <p> $F \text{ см}^2 = 2.919$ $Q \text{ кг.} = 0.791$ $D \text{ оп.мм} = 46.0$ $P \text{ н.мм} = 219.2$ $P \text{ вн.мм} = 55.0$ Гр. сл. = V Точн. = П </p>		<p>ПЗ-20</p> <p> $F \text{ см}^2 = 2.919$ $Q \text{ кг.} = 0.791$ $D \text{ оп.мм} = 46.0$ $P \text{ н.мм} = 219.2$ $P \text{ вн.мм} = 55.0$ Гр. сл. = V Точн. = П </p>










	<p>ПЗ-21</p> <p> $F \text{ см}^2 = 2.779$ $Q \text{ кг.} = 0.753$ $D \text{ оп.мм} = 47.0$ $P \text{ н.мм} = 177.3$ $P \text{ вн.мм} = 93.1$ Гр. сл. = V Точн. = П </p>		<p>ПЗ-26</p> <p> $F \text{ см}^2 = 2.650$ $Q \text{ кг.} = 0.718$ $D \text{ оп.мм} = 100.0$ $P \text{ н.мм} = 229.6$ $P \text{ вн.мм} = 45.2$ Гр. сл. = V Точн. = Н </p>
	<p>ПЗ-22</p> <p> $F \text{ см}^2 = 2.065$ $Q \text{ кг.} = 0.560$ $D \text{ оп.мм} = 36.0$ $P \text{ н.мм} = 135.0$ $P \text{ вн.мм} = 64.0$ Гр. сл. = IV Точн. = П </p>		<p>ПЗ-27</p> <p> $F \text{ см}^2 = 3.290$ $Q \text{ кг.} = 0.892$ $D \text{ оп.мм} = 50.0$ $P \text{ н.мм} = 250.0$ $P \text{ вн.мм} = 64.0$ Гр. сл. = V Точн. = П </p>
	<p>ПЗ-23</p> <p> $F \text{ см}^2 = 2.665$ $Q \text{ кг.} = 0.722$ $D \text{ оп.мм} = 50.0$ $P \text{ н.мм} = 195.0$ $P \text{ вн.мм} = 64.0$ Гр. сл. = V Точн. = П </p>		<p>ПЗ-28</p> <p> $F \text{ см}^2 = 6.245$ $Q \text{ кг.} = 1.692$ $D \text{ оп.мм} = 80.0$ $P \text{ н.мм} = 387.0$ $P \text{ вн.мм} = 192.0$ Гр. сл. = VI Точн. = П </p>
	<p>ПЗ-24</p> <p> $F \text{ см}^2 = 2.690$ $Q \text{ кг.} = 0.729$ $D \text{ оп.мм} = 46.0$ $P \text{ н.мм} = 190.0$ $P \text{ вн.мм} = 64.0$ Гр. сл. = IV Точн. = П </p>		<p>ПЗ-29</p> <p> $F \text{ см}^2 = 7.720$ $Q \text{ кг.} = 2.092$ $D \text{ оп.мм} = 80.0$ $P \text{ н.мм} = 512.0$ $P \text{ вн.мм} = 192.0$ Гр. сл. = VI Точн. = П </p>
	<p>ПЗ-25</p> <p> $F \text{ см}^2 = 2.365$ $Q \text{ кг.} = 0.641$ $D \text{ оп.мм} = 42.0$ $P \text{ н.мм} = 165.0$ $P \text{ вн.мм} = 64.0$ Гр. сл. = V Точн. = П </p>		<p>ПЗ-30</p> <p> $F \text{ см}^2 = 2.990$ $Q \text{ кг.} = 0.810$ $D \text{ оп.мм} = 48.0$ $P \text{ н.мм} = 220.0$ $P \text{ вн.мм} = 64.0$ Гр. сл. = V Точн. = П </p>











	<p>ПЗ-31</p> <p> $F \text{ см}^2 = 2.840$ $Q \text{ кг.} = 0.770$ $D \text{ оп.мм} = 42.4$ $P \text{ н.мм} = 208.6$ $P \text{ вн.мм} = 64.0$ Гр. сл. = V Точн. = П </p>		<p>ПЗ-36</p> <p> $F \text{ см}^2 = 2.340$ $Q \text{ кг.} = 0.634$ $D \text{ оп.мм} = 38.8$ $P \text{ н.мм} = 154.6$ $P \text{ вн.мм} = 15.7$ Гр. сл. = V Точн. = П </p>
	<p>ПЗ-32</p> <p> $F \text{ см}^2 = 5.990$ $Q \text{ кг.} = 1.623$ $D \text{ оп.мм} = 52.0$ $P \text{ н.мм} = 389.6$ $P \text{ вн.мм} = 96.0$ Гр. сл. = VI Точн. = П </p>		<p>ПЗ-37</p> <p> $F \text{ см}^2 = 1.324$ $Q \text{ кг.} = 0.359$ $D \text{ оп.мм} = 40.0$ $P \text{ н.мм} = 97.0$ $P \text{ вн.мм} = 15.7$ Гр. сл. = V Точн. = П </p>
	<p>ПЗ-33</p> <p> $F \text{ см}^2 = 4.533$ $Q \text{ кг.} = 1.228$ $D \text{ оп.мм} = 49.0$ $P \text{ н.мм} = 376.3$ $P \text{ вн.мм} = 64.0$ Гр. сл. = VI Точн. = П </p>		<p>ПЗ-38</p> <p> $F \text{ см}^2 = 3.427$ $Q \text{ кг.} = 0.928$ $D \text{ оп.мм} = 49.0$ $P \text{ н.мм} = 258.2$ $P \text{ вн.мм} = 69.26$ Гр. сл. = 0соб. Точн. = П </p>
	<p>ПЗ-34</p> <p> $F \text{ см}^2 = 3.616$ $Q \text{ кг.} = 0.980$ $D \text{ оп.мм} = 46.7$ $P \text{ н.мм} = 282.3$ $P \text{ вн.мм} = 64.0$ Гр. сл. = VI Точн. = П </p>		<p>ПЗ-39</p> <p> $F \text{ см}^2 = 3.712$ $Q \text{ кг.} = 1.006$ $D \text{ оп.мм} = 67.0$ $P \text{ н.мм} = 314.6$ $P \text{ вн.мм} = 66.4$ Гр. сл. = 0соб. Точн. = П </p>
	<p>ПЗ-35</p> <p> $F \text{ см}^2 = 4.770$ $Q \text{ кг.} = 1.293$ $D \text{ оп.мм} = 80.0$ $P \text{ н.мм} = 262.0$ $P \text{ вн.мм} = 192.0$ Гр. сл. = VI Точн. = П </p>		<p>ПЗ-40</p> <p> $F \text{ см}^2 = 8.740$ $Q \text{ кг.} = 2.369$ $D \text{ оп.мм} = 190.0$ $P \text{ н.мм} = 581.7$ $P \text{ вн.мм} = 245.3$ Гр. сл. = 0соб. Точн. = П </p>











	<p>ПЗ-41</p> <p> $F \text{ см}^2 = 7.446$ $Q \text{ кг.} = 2.018$ $D \text{ оп.мм} = 168.0$ $P \text{ н.мм} = 502.1$ $P \text{ вн.мм} = 227.4$ Гр. сл. = 0соб. Точн. = П </p>		<p>ПЗ-46</p> <p> $F \text{ см}^2 = 2.289$ $Q \text{ кг.} = 0.620$ $D \text{ оп.мм} = 50.0$ $P \text{ н.мм} = 204.0$ $P \text{ вн.мм} = 134.0$ Гр. сл. = V Точн. = П </p>
	<p>ПЗ-42</p> <p> $F \text{ см}^2 = 2.557$ $Q \text{ кг.} = 0.693$ $D \text{ оп.мм} = 38.8$ $P \text{ н.мм} = 156.3$ $P \text{ вн.мм} = 40.0$ Гр. сл. = 0соб. Точн. = П </p>		<p>ПЗ-47</p> <p> $F \text{ см}^2 = 1.324$ $Q \text{ кг.} = 0.359$ $D \text{ оп.мм} = 31.0$ $P \text{ н.мм} = 120.0$ $P \text{ вн.мм} = 72.0$ Гр. сл. = V Точн. = П </p>
	<p>ПЗ-43</p> <p> $F \text{ см}^2 = 1.340$ $Q \text{ кг.} = 0.363$ $D \text{ оп.мм} = 31.0$ $P \text{ н.мм} = 72.5$ $P \text{ вн.мм} = 18.9$ Гр. сл. = IV Точн. = Н </p>		<p>ПЗ-48</p> <p> $F \text{ см}^2 = 1.813$ $Q \text{ кг.} = 0.518$ $D \text{ оп.мм} = 46$ $P \text{ н.мм} = 151$ $P \text{ вн.мм} = 134$ Гр. сл. = V Точн. = П </p>
	<p>ПЗ-44</p> <p> $F \text{ см}^2 = 1.430$ $Q \text{ кг.} = 0.388$ $D \text{ оп.мм} = 31.0$ $P \text{ н.мм} = 75.0$ $P \text{ вн.мм} = 18.9$ Гр. сл. = IV Точн. = Н </p>		<p>ПЗ-49</p> <p> $F \text{ см}^2 = 7.025$ $Q \text{ кг.} = 1.904$ $D \text{ оп.мм} = 111.6$ $P \text{ н.мм} = 422.8$ $P \text{ вн.мм} = 184.5$ Гр. сл. = V Точн. = П </p>
	<p>ПЗ-45</p> <p> $F \text{ см}^2 = 4.900$ $Q \text{ кг.} = 1.328$ $D \text{ оп.мм} = 85.5$ $P \text{ н.мм} = 330.1$ $P \text{ вн.мм} = 188.3$ Гр. сл. = V Точн. = Н </p>		<p>ПЗ-50</p> <p> $F \text{ см}^2 = 9.457$ $Q \text{ кг.} = 2.563$ $D \text{ оп.мм} = 135.5$ $P \text{ н.мм} = 522.8$ $P \text{ вн.мм} = 284.9$ Гр. сл. = V Точн. = П </p>











	<p>ПЗ-51</p> <p> $F \text{ см}^2 = 9.285$ $Q \text{ кг.} = 2.516$ $D \text{ оп.мм} = 97.1$ $P \text{ н.мм} = 647.6$ $P \text{ вн.мм} = 188.5$ Гр. сл. = V Точн. = П </p>		<p>ПЗ-56</p> <p> $F \text{ см}^2 = 0.823$ $Q \text{ кг.} = 0.223$ $D \text{ оп.мм} = 23.3$ $P \text{ н.мм} = 93.2$ $P \text{ вн.мм} = 34.5$ Гр. сл. = V Точн. = П </p>
	<p>ПЗ-52</p> <p> $F \text{ см}^2 = 4.083$ $Q \text{ кг.} = 1.106$ $D \text{ оп.мм} = 57.8$ $P \text{ н.мм} = 257.4$ $P \text{ вн.мм} = 133.4$ Гр. сл. = V Точн. = П </p>		
	<p>ПЗ-53</p> <p> $F \text{ см}^2 = 6.023$ $Q \text{ кг.} = 1.632$ $D \text{ оп.мм} = 86.5$ $P \text{ н.мм} = 327.4$ $P \text{ вн.мм} = 206.1$ Гр. сл. = V Точн. = П </p>		<p>ПЗ-58</p> <p> $F \text{ см}^2 = 2.663$ $Q \text{ кг.} = 0.722$ $D \text{ оп.мм} = 57.0$ $P \text{ н.мм} = 214.2$ $P \text{ вн.мм} = 134.7$ Гр. сл. = IV Точн. = П </p>
	<p>ПЗ-54</p> <p> $F \text{ см}^2 = 7.309$ $Q \text{ кг.} = 1.981$ $D \text{ оп.мм} = 109.7$ $P \text{ н.мм} = 377.4$ $P \text{ вн.мм} = 253.5$ Гр. сл. = V Точн. = П </p>		<p>ПЗ-59</p> <p> $F \text{ см}^2 = 2.982$ $Q \text{ кг.} = 0.808$ $D \text{ оп.мм} = 57.0$ $P \text{ н.мм} = 258.0$ $P \text{ вн.мм} = 142.0$ Гр. сл. = IV Точн. = П </p>
	<p>ПЗ-55</p> <p> $F \text{ см}^2 = 3.758$ $Q \text{ кг.} = 1.018$ $D \text{ оп.мм} = 53.3$ $P \text{ н.мм} = 153.4$ $P \text{ вн.мм} = 168.6$ Гр. сл. = V Точн. = П </p>		<p>ПЗ-60</p> <p> $F \text{ см}^2 = 3.300$ $Q \text{ кг.} = 0.894$ $D \text{ оп.мм} = 55.0$ $P \text{ н.мм} = 157.8$ $P \text{ вн.мм} = 34.6$ Гр. сл. = IV Точн. = П </p>











	<p>ПЗ-61</p> <p> $F \text{ см}^2 = 2.790$ $Q \text{ кг.} = 0.756$ $D \text{ оп.мм} = 64.0$ $P \text{ н.мм} = 228.2$ $P \text{ вн.мм} = 135.4$ Гр. сл. = IV Точн. = П </p>		<p>ПЗ-66</p> <p> $F \text{ см}^2 = 3.301$ $Q \text{ кг.} = 0.895$ $D \text{ оп.мм} = 69.0$ $P \text{ н.мм} = 255.6$ $P \text{ вн.мм} = 178.0$ Гр. сл. = IV Точн. = П </p>
			<p>ПЗ-67</p> <p> $F \text{ см}^2 = 5.382$ $Q \text{ кг.} = 1.459$ $D \text{ оп.мм} = 126.0$ $P \text{ н.мм} = 418.0$ $P \text{ вн.мм} = 302.0$ Гр. сл. = IV Точн. = П </p>
	<p>ПЗ-63</p> <p> $F \text{ см}^2 = 3.879$ $Q \text{ кг.} = 1.051$ $D \text{ оп.мм} = 55.5$ $P \text{ н.мм} = 215.8$ $P \text{ вн.мм} = 115.4$ Гр. сл. = VI Точн. = П </p>		<p>ПЗ-68</p> <p> $F \text{ см}^2 = 4.238$ $Q \text{ кг.} = 1.148$ $D \text{ оп.мм} = 68.0$ $P \text{ н.мм} = 294.9$ $P \text{ вн.мм} = 154.0$ Гр. сл. = V Точн. = Н </p>
	<p>ПЗ-64</p> <p> $F \text{ см}^2 = 2.618$ $Q \text{ кг.} = 0.709$ $D \text{ оп.мм} = 45.0$ $P \text{ н.мм} = 198.5$ $P \text{ вн.мм} = 62.4$ Гр. сл. = 0соб. Точн. = Н </p>		<p>ПЗ-69</p> <p> $F \text{ см}^2 = 2.200$ $Q \text{ кг.} = 0.596$ $D \text{ оп.мм} = 30.0$ $P \text{ н.мм} = 140.2$ $P \text{ вн.мм} = 172.0$ Гр. сл. = 0соб. Точн. = П </p>
	<p>ПЗ-65</p> <p> $F \text{ см}^2 = 13.962$ $Q \text{ кг.} = 3.784$ $D \text{ оп.мм} = 80.0$ $P \text{ н.мм} = 233.9$ $P \text{ вн.мм} = 172.8$ Гр. сл. = IV Точн. = П </p>		<p>ПЗ-70</p> <p> $F \text{ см}^2 = 2.492$ $Q \text{ кг.} = 0.675$ $D \text{ оп.мм} = 94.0$ $P \text{ н.мм} = 223.0$ $P \text{ вн.мм} = 190.0$ Гр. сл. = V Точн. = П </p>











	<p>ПЗ-71</p> <p> $F \text{ см}^2 = 1.711$ $Q \text{ кг.} = 0.464$ $D \text{ оп.мм} = 50.0$ $P \text{ н.мм} = 256.0$ $P \text{ вн.мм} = 0.0$ Гр. сл. = 0соб. Точн. = П </p>		<p>ПЗ-76</p> <p> $F \text{ см}^2 = 6.455$ $Q \text{ кг.} = 1.749$ $D \text{ оп.мм} = 61.6$ $P \text{ н.мм} = 175.0$ $P \text{ вн.мм} = 147.6$ Гр. сл. = V Точн. = П </p>
	<p>ПЗ-72</p> <p> $F \text{ см}^2 = 2.587$ $Q \text{ кг.} = 0.701$ $D \text{ оп.мм} = 55.0$ $P \text{ н.мм} = 129.6$ $P \text{ вн.мм} = 34.6$ Гр. сл. = IV Точн. = П </p>		<p>ПЗ-77</p> <p> $F \text{ см}^2 = 9.677$ $Q \text{ кг.} = 2.622$ $D \text{ оп.мм} = 129.3$ $P \text{ н.мм} = 429.3$ $P \text{ вн.мм} = 294.4$ Гр. сл. = V Точн. = П </p>
	<p>ПЗ-73</p> <p> $F \text{ см}^2 = 2.740$ $Q \text{ кг.} = 0.743$ $D \text{ оп.мм} = 55.0$ $P \text{ н.мм} = 133.3$ $P \text{ вн.мм} = 34.6$ Гр. сл. = IV Точн. = П </p>		<p>ПЗ-78</p> <p> $F \text{ см}^2 = 3.734$ $Q \text{ кг.} = 1.012$ $D \text{ оп.мм} = 85.0$ $P \text{ н.мм} = 461.6$ $P \text{ вн.мм} = 0.0$ Гр. сл. = 0соб. Точн. = П </p>
			<p>ПЗ-79</p> <p> $F \text{ см}^2 = 8.222$ $Q \text{ кг.} = 2.228$ $D \text{ оп.мм} = 111.6$ $P \text{ н.мм} = 472.8$ $P \text{ вн.мм} = 233.0$ Гр. сл. = V Точн. = П </p>
	<p>ПЗ-75</p> <p> $F \text{ см}^2 = 14.285$ $Q \text{ кг.} = 3.871$ $D \text{ оп.мм} = 149.1$ $P \text{ н.мм} = 371.0$ $P \text{ вн.мм} = 341.6$ Гр. сл. = V Точн. = П </p>		<p>ПЗ-80</p> <p> $F \text{ см}^2 = 11.447$ $Q \text{ кг.} = 3.102$ $D \text{ оп.мм} = 159.8$ $P \text{ н.мм} = 572.8$ $P \text{ вн.мм} = 331.0$ Гр. сл. = V Точн. = П </p>











	<p>ПЗ-81</p> <p> $F \text{ см}^2 = 13.330$ $Q \text{ кг.} = 3.612$ $D \text{ оп.мм} = 184.2$ $P \text{ н.мм} = 622.8$ $P \text{ вн.мм} = 378.5$ Гр. сл. = V Точн. = П </p>		<p>ПЗ-86</p> <p> $F \text{ см}^2 = 2.663$ $Q \text{ кг.} = 0.722$ $D \text{ оп.мм} = 56.1$ $P \text{ н.мм} = 189.1$ $P \text{ вн.мм} = 123.6$ Гр. сл. = V Точн. = П </p>
	<p>ПЗ-82</p> <p> $F \text{ см}^2 = 8.445$ $Q \text{ кг.} = 2.289$ $D \text{ оп.мм} = 81.6$ $P \text{ н.мм} = 225.0$ $P \text{ вн.мм} = 195.6$ Гр. сл. = V Точн. = П </p>		<p>ПЗ-87</p> <p> $F \text{ см}^2 = 2.809$ $Q \text{ кг.} = 0.761$ $D \text{ оп.мм} = 58.5$ $P \text{ н.мм} = 198.1$ $P \text{ вн.мм} = 132.0$ Гр. сл. = V Точн. = П </p>
	<p>ПЗ-83</p> <p> $F \text{ см}^2 = 10.445$ $Q \text{ кг.} = 2.831$ $D \text{ оп.мм} = 103.8$ $P \text{ н.мм} = 275.0$ $P \text{ вн.мм} = 245.6$ Гр. сл. = V Точн. = П </p>		<p>ПЗ-88</p> <p> $F \text{ см}^2 = 6.285$ $Q \text{ кг.} = 1.703$ $D \text{ оп.мм} = 60.1$ $P \text{ н.мм} = 171.0$ $P \text{ вн.мм} = 141.6$ Гр. сл. = V Точн. = П </p>
	<p>ПЗ-84</p> <p> $F \text{ см}^2 = 12.365$ $Q \text{ кг.} = 3.351$ $D \text{ оп.мм} = 126.2$ $P \text{ н.мм} = 323.0$ $P \text{ вн.мм} = 293.6$ Гр. сл. = V Точн. = П </p>		<p>ПЗ-89</p> <p> $F \text{ см}^2 = 2.690$ $Q \text{ кг.} = 0.729$ $D \text{ оп.мм} = 56.0$ $P \text{ н.мм} = 253.0$ $P \text{ вн.мм} = 147.0$ Гр. сл. = V Точн. = П </p>
	<p>ПЗ-85</p> <p> $F \text{ см}^2 = 1.381$ $Q \text{ кг.} = 0.374$ $D \text{ оп.мм} = 36.8$ $P \text{ н.мм} = 128.9$ $P \text{ вн.мм} = 59.1$ Гр. сл. = V Точн. = П </p>		<p>ПЗ-90</p> <p> $F \text{ см}^2 = 1.974$ $Q \text{ кг.} = 0.535$ $D \text{ оп.мм} = 46.9$ $P \text{ н.мм} = 152.6$ $P \text{ вн.мм} = 88.4$ Гр. сл. = V Точн. = П </p>











	<p>ПЗ-91</p> <p> $F \text{ см}^2 = 2.044$ $Q \text{ кг.} = 0.554$ $D \text{ оп.мм} = 46.9$ $P \text{ н.мм} = 158.0$ $P \text{ вн.мм} = 93.0$ Гр. сл. = V Точн. = П </p>		<p>ПЗ-96</p> <p> $F \text{ см}^2 = 2.050$ $Q \text{ кг.} = 0.556$ $D \text{ оп.мм} = 37.0$ $P \text{ н.мм} = 109.9$ $P \text{ вн.мм} = 99.1$ Гр. сл. = V Точн. = П </p>
	<p>ПЗ-92</p> <p> $F \text{ см}^2 = 3.432$ $Q \text{ кг.} = 0.930$ $D \text{ оп.мм} = 52.8$ $P \text{ н.мм} = 236.8$ $P \text{ вн.мм} = 93.4$ Гр. сл. = V Точн. = П </p>		<p>ПЗ-97</p> <p> $F \text{ см}^2 = 23.600$ $Q \text{ кг.} = 6.396$ $D \text{ оп.мм} = 187.0$ $P \text{ н.мм} = 504.0$ $P \text{ вн.мм} = 566.0$ Гр. сл. = V Точн. = П </p>
	<p>ПЗ-93</p> <p> $F \text{ см}^2 = 2.537$ $Q \text{ кг.} = 0.688$ $D \text{ оп.мм} = 40.0$ $P \text{ н.мм} = 113.1$ $P \text{ вн.мм} = 110.1$ Гр. сл. = V Точн. = П </p>		<p>ПЗ-98</p> <p> $F \text{ см}^2 = 17.600$ $Q \text{ кг.} = 4.770$ $D \text{ оп.мм} = 130.0$ $P \text{ н.мм} = 384.0$ $P \text{ вн.мм} = 446.0$ Гр. сл. = V Точн. = П </p>
	<p>ПЗ-94</p> <p> $F \text{ см}^2 = 5.387$ $Q \text{ кг.} = 1.460$ $D \text{ оп.мм} = 80.0$ $P \text{ н.мм} = 345.7$ $P \text{ вн.мм} = 180.3$ Гр. сл. = VI Точн. = П </p>		<p>ПЗ-99</p> <p> $F \text{ см}^2 = 1.340$ $Q \text{ кг.} = 0.363$ $D \text{ оп.мм} = 27.0$ $P \text{ н.мм} = 98.0$ $P \text{ вн.мм} = 36.0$ Гр. сл. = V Точн. = П </p>
	<p>ПЗ-95</p> <p> $F \text{ см}^2 = 0.324$ $Q \text{ кг.} = 0.088$ $D \text{ оп.мм} = 8.0$ $P \text{ н.мм} = 25.1$ $P \text{ вн.мм} = 38.8$ Гр. сл. = 0соб. Точн. = П </p>		<p>ПЗ-100</p> <p> $F \text{ см}^2 = 1.760$ $Q \text{ кг.} = 0.477$ $D \text{ оп.мм} = 37.0$ $P \text{ н.мм} = 126.0$ $P \text{ вн.мм} = 36.0$ Гр. сл. = V Точн. = П </p>











	<p>ПЗ-101</p> <p> $F \text{ см}^2 = 8.588$ $Q \text{ кг.} = 2.327$ $D \text{ оп.мм} = 127.0$ $P \text{ н.мм} = 319.7$ $P \text{ вн.мм} = 323.1$ Гр. сл. = V Точн. = П </p>		<p>ПЗ-106</p> <p> $F \text{ см}^2 = 4.963$ $Q \text{ кг.} = 1.345$ $D \text{ оп.мм} = 73.0$ $P \text{ н.мм} = 181.3$ $P \text{ вн.мм} = 207.3$ Гр. сл. = 0соб. Точн. = П </p>
	<p>ПЗ-102</p> <p> $F \text{ см}^2 = 7.339$ $Q \text{ кг.} = 1.989$ $D \text{ оп.мм} = 127.0$ $P \text{ н.мм} = 307.8$ $P \text{ вн.мм} = 344.7$ Гр. сл. = V Точн. = П </p>		<p>ПЗ-107</p> <p> $F \text{ см}^2 = 8.719$ $Q \text{ кг.} = 2.363$ $D \text{ оп.мм} = 160.0$ $P \text{ н.мм} = 365.5$ $P \text{ вн.мм} = 304.7$ Гр. сл. = 0соб. Точн. = Н </p>
	<p>ПЗ-103</p> <p> $F \text{ см}^2 = 1.421$ $Q \text{ кг.} = 0.385$ $D \text{ оп.мм} = 35.4$ $P \text{ н.мм} = 158.5$ $P \text{ вн.мм} = 68.9$ Гр. сл. = 0соб. Точн. = П </p>		<p>ПЗ-108</p> <p> $F \text{ см}^2 = 3.384$ $Q \text{ кг.} = 0.917$ $D \text{ оп.мм} = 53.0$ $P \text{ н.мм} = 169.3$ $P \text{ вн.мм} = 156.1$ Гр. сл. = 0соб. Точн. = Н </p>
	<p>ПЗ-104</p> <p> $F \text{ см}^2 = 1.609$ $Q \text{ кг.} = 0.436$ $D \text{ оп.мм} = 42.8$ $P \text{ н.мм} = 188.8$ $P \text{ вн.мм} = 70.9$ Гр. сл. = VI Точн. = П </p>		<p>ПЗ-109</p> <p> $F \text{ см}^2 = 7.001$ $Q \text{ кг.} = 1.897$ $D \text{ оп.мм} = 126.2$ $P \text{ н.мм} = 502.6$ $P \text{ вн.мм} = 26.3$ Гр. сл. = V Точн. = П </p>
	<p>ПЗ-105</p> <p> $F \text{ см}^2 = 2.327$ $Q \text{ кг.} = 0.631$ $D \text{ оп.мм} = 41.0$ $P \text{ н.мм} = 193.9$ $P \text{ вн.мм} = 0.0$ Гр. сл. = 0соб. Точн. = П </p>		<p>ПЗ-110</p> <p> $F \text{ см}^2 = 1.389$ $Q \text{ кг.} = 0.376$ $D \text{ оп.мм} = 33.0$ $P \text{ н.мм} = 121.4$ $P \text{ вн.мм} = 85.3$ Гр. сл. = 0соб. Точн. = П </p>








	<p>ПЗ-111</p> <p> $F \text{ см}^2 = 4.961$ $Q \text{ кг.} = 1.344$ $D \text{ оп.мм} = 93.0$ $P \text{ н.мм} = 266.6$ $P \text{ вн.мм} = 166.0$ Гр. сл. = 0соб. Точн. = П </p>		<p>ПЗ-116</p> <p> $F \text{ см}^2 = 2.962$ $Q \text{ кг.} = 0.803$ $D \text{ оп.мм} = 43.4$ $P \text{ н.мм} = 143.0$ $P \text{ вн.мм} = 120.4$ Гр. сл. = V Точн. = П </p>
	<p>ПЗ-112</p> <p> $F \text{ см}^2 = 37.692$ $Q \text{ кг.} = 10.215$ $D \text{ оп.мм} = 160.0$ $P \text{ н.мм} = 418.6$ $P \text{ вн.мм} = 340.6$ Гр. сл. = V Точн. = П </p>		<p>ПЗ-117</p> <p> $F \text{ см}^2 = 1.196$ $Q \text{ кг.} = 0.324$ $D \text{ оп.мм} = 27.7$ $P \text{ н.мм} = 94.0$ $P \text{ вн.мм} = 26.8$ Гр. сл. = V Точн. = П </p>
	<p>ПЗ-113</p> <p> $F \text{ см}^2 = 2.444$ $Q \text{ кг.} = 0.662$ $D \text{ оп.мм} = 35.0$ $P \text{ н.мм} = 91.0$ $P \text{ вн.мм} = 18.9$ Гр. сл. = IV Точн. = П </p>		<p>ПЗ-118</p> <p> $F \text{ см}^2 = 4.000$ $Q \text{ кг.} = 1.084$ $D \text{ оп.мм} = 75.8$ $P \text{ н.мм} = 277.5$ $P \text{ вн.мм} = 152.1$ Гр. сл. = V Точн. = П </p>
	<p>ПЗ-114</p> <p> $F \text{ см}^2 = 5.728$ $Q \text{ кг.} = 1.552$ $D \text{ оп.мм} = 74.0$ $P \text{ н.мм} = 263.5$ $P \text{ вн.мм} = 18.9$ Гр. сл. = V Точн. = П </p>		<p>ПЗ-119</p> <p> $F \text{ см}^2 = 5.109$ $Q \text{ кг.} = 1.385$ $D \text{ оп.мм} = 128.4$ $P \text{ н.мм} = 348.1$ $P \text{ вн.мм} = 211.9$ Гр. сл. = V Точн. = П </p>
	<p>ПЗ-115</p> <p> $F \text{ см}^2 = 4.036$ $Q \text{ кг.} = 1.094$ $D \text{ оп.мм} = 82.0$ $P \text{ н.мм} = 272.8$ $P \text{ вн.мм} = 193.0$ Гр. сл. = 0соб. Точн. = П </p>		<p>ПЗ-120</p> <p> $F \text{ см}^2 = 6.406$ $Q \text{ кг.} = 1.736$ $D \text{ оп.мм} = 111.1$ $P \text{ н.мм} = 367.6$ $P \text{ вн.мм} = 303.9$ Гр. сл. = V Точн. = П </p>

	<p>ПЗ-121</p> <p> $F \text{ см}^2 = 2.841$ $Q \text{ кг.} = 0.770$ $D \text{ оп.мм} = 45.0$ $P \text{ н.мм} = 215.6$ $P \text{ вн.мм} = 93.9$ Гр. сл. = V Точн. = П </p>		<p>ПЗ-126</p> <p> $F \text{ см}^2 = 2.384$ $Q \text{ кг.} = 0.646$ $D \text{ оп.мм} = 55.7$ $P \text{ н.мм} = 168.8$ $P \text{ вн.мм} = 89.8$ Гр. сл. = V Точн. = П </p>
	<p>ПЗ-122</p> <p> $F \text{ см}^2 = 2.504$ $Q \text{ кг.} = 0.679$ $D \text{ оп.мм} = 74.1$ $P \text{ н.мм} = 258.3$ $P \text{ вн.мм} = 48.0$ Гр. сл. = V Точн. = П </p>		<p>ПЗ-127</p> <p> $F \text{ см}^2 = 2.028$ $Q \text{ кг.} = 0.550$ $D \text{ оп.мм} = 53.0$ $P \text{ н.мм} = 196.1$ $P \text{ вн.мм} = 48.0$ Гр. сл. = V Точн. = П </p>
	<p>ПЗ-123</p> <p> $F \text{ см}^2 = 4.500$ $Q \text{ кг.} = 1.220$ $D \text{ оп.мм} = 46.2$ $P \text{ н.мм} = 96.8$ $P \text{ вн.мм} = 28.0$ Гр. сл. = V Точн. = П </p>		<p>ПЗ-128</p> <p> $F \text{ см}^2 = 1.839$ $Q \text{ кг.} = 0.498$ $D \text{ оп.мм} = 46.4$ $P \text{ н.мм} = 163.2$ $P \text{ вн.мм} = 57.3$ Гр. сл. = V Точн. = П </p>
	<p>ПЗ-124</p> <p> $F \text{ см}^2 = 3.278$ $Q \text{ кг.} = 0.888$ $D \text{ оп.мм} = 90.1$ $P \text{ н.мм} = 276.0$ $P \text{ вн.мм} = 101.1$ Гр. сл. = V Точн. = П </p>		<p>ПЗ-129</p> <p> $F \text{ см}^2 = 3.235$ $Q \text{ кг.} = 0.877$ $D \text{ оп.мм} = 45.0$ $P \text{ н.мм} = 253.5$ $P \text{ вн.мм} = 117.6$ Гр. сл. = V Точн. = П </p>
	<p>ПЗ-125</p> <p> $F \text{ см}^2 = 3.644$ $Q \text{ кг.} = 0.988$ $D \text{ оп.мм} = 32.0$ $P \text{ н.мм} = 232.6$ $P \text{ вн.мм} = 146.5$ Гр. сл. = V Точн. = П </p>		<p>ПЗ-130</p> <p> $F \text{ см}^2 = 2.720$ $Q \text{ кг.} = 0.737$ $D \text{ оп.мм} = 47.0$ $P \text{ н.мм} = 208.0$ $P \text{ вн.мм} = 95.6$ Гр. сл. = IV Точн. = П </p>

	<p>ПЗ-131</p> <p> $F \text{ см}^2 = 1.799$ $Q \text{ кг.} = 0.488$ $D \text{ оп.мм} = 31.0$ $P \text{ н.мм} = 148.0$ $P \text{ вн.мм} = 47.4$ Гр. сл. = IV Точн. = П </p>		<p>ПЗ-136</p> <p> $F \text{ см}^2 = 9.680$ $Q \text{ кг.} = 2.623$ $D \text{ оп.мм} = 111.0$ $P \text{ н.мм} = 369.0$ $P \text{ вн.мм} = 84.0$ Гр. сл. = V Точн. = Н </p>
	<p>ПЗ-132</p> <p> $F \text{ см}^2 = 1.868$ $Q \text{ кг.} = 0.506$ $D \text{ оп.мм} = 28.0$ $P \text{ н.мм} = 96.0$ $P \text{ вн.мм} = 43.5$ Гр. сл. = IV Точн. = П </p>		<p>ПЗ-137</p> <p> $F \text{ см}^2 = 1.857$ $Q \text{ кг.} = 0.503$ $D \text{ оп.мм} = 40.0$ $P \text{ н.мм} = 177.3$ $P \text{ вн.мм} = 50.2$ Гр. сл. = 0соб. Точн. = П </p>
	<p>ПЗ-133</p> <p> $F \text{ см}^2 = 8.234$ $Q \text{ кг.} = 2.231$ $D \text{ оп.мм} = 43.4$ $P \text{ н.мм} = 213.9$ $P \text{ вн.мм} = 81.8$ Гр. сл. = V Точн. = П </p>		<p>ПЗ-138</p> <p> $F \text{ см}^2 = 0.346$ $Q \text{ кг.} = 0.094$ $D \text{ оп.мм} = 12.0$ $P \text{ н.мм} = 37.7$ $P \text{ вн.мм} = 31.4$ Гр. сл. = V Точн. = П </p>
	<p>ПЗ-134</p> <p> $F \text{ см}^2 = 3.840$ $Q \text{ кг.} = 1.041$ $D \text{ оп.мм} = 84.5$ $P \text{ н.мм} = 503.3$ $P \text{ вн.мм} = 0.0$ Гр. сл. = 0соб. Точн. = П </p>		<p>ПЗ-139</p> <p> $F \text{ см}^2 = 12.166$ $Q \text{ кг.} = 3.297$ $D \text{ оп.мм} = 98.0$ $P \text{ н.мм} = 311.7$ $P \text{ вн.мм} = 277.6$ Гр. сл. = 0соб. Точн. = П </p>
	<p>ПЗ-135</p> <p> $F \text{ см}^2 = 16.300$ $Q \text{ кг.} = 4.417$ $D \text{ оп.мм} = 125.0$ $P \text{ н.мм} = 452.6$ $P \text{ вн.мм} = 157.4$ Гр. сл. = 0соб. Точн. = Н </p>		<p>ПЗ-140</p> <p> $F \text{ см}^2 = 3.792$ $Q \text{ кг.} = 1.028$ $D \text{ оп.мм} = 97.0$ $P \text{ н.мм} = 379.0$ $P \text{ вн.мм} = 175.5$ Гр. сл. = VI Точн. = П </p>

	<p>ПЗ-141</p> <p> $F \text{ см}^2 = 2.700$ $Q \text{ кг.} = 0.732$ $D \text{ оп.мм} = 57.0$ $P \text{ н.мм} = 219.0$ $P \text{ вн.мм} = 134.7$ Гр. сл. = IV Точн. = П </p>		<p>ПЗ-146</p> <p> $F \text{ см}^2 = 3.563$ $Q \text{ кг.} = 0.966$ $D \text{ оп.мм} = 56.9$ $P \text{ н.мм} = 247.4$ $P \text{ вн.мм} = 125.1$ Гр. сл. = V Точн. = П </p>
	<p>ПЗ-142</p> <p> $F \text{ см}^2 = 1.576$ $Q \text{ кг.} = 0.427$ $D \text{ оп.мм} = 30.0$ $P \text{ н.мм} = 146.6$ $P \text{ вн.мм} = 36.0$ Гр. сл. = 0соб. Точн. = П </p>		<p>ПЗ-147</p> <p> $F \text{ см}^2 = 4.068$ $Q \text{ кг.} = 1.102$ $D \text{ оп.мм} = 37.0$ $P \text{ н.мм} = 95.4$ $P \text{ вн.мм} = 34.0$ Гр. сл. = III Точн. = П </p>
	<p>ПЗ-143</p> <p> $F \text{ см}^2 = 2.164$ $Q \text{ кг.} = 0.586$ $D \text{ оп.мм} = 45.0$ $P \text{ н.мм} = 182.0$ $P \text{ вн.мм} = 68.0$ Гр. сл. = 0соб. Точн. = П </p>		<p>ПЗ-148</p> <p> $F \text{ см}^2 = 1.965$ $Q \text{ кг.} = 0.533$ $D \text{ оп.мм} = 38.5$ $P \text{ н.мм} = 146.4$ $P \text{ вн.мм} = 40.0$ Гр. сл. = VI Точн. = П </p>
	<p>ПЗ-144</p> <p> $F \text{ см}^2 = 2.755$ $Q \text{ кг.} = 0.747$ $D \text{ оп.мм} = 28.1$ $P \text{ н.мм} = 216.4$ $P \text{ вн.мм} = 142.2$ Гр. сл. = V Точн. = П </p>		<p>ПЗ-149</p> <p> $F \text{ см}^2 = 3.799$ $Q \text{ кг.} = 1.030$ $D \text{ оп.мм} = 72.0$ $P \text{ н.мм} = 282.7$ $P \text{ вн.мм} = 104.0$ Гр. сл. = 0соб. Точн. = П </p>
	<p>ПЗ-145</p> <p> $F \text{ см}^2 = 5.088$ $Q \text{ кг.} = 1.379$ $D \text{ оп.мм} = 90.1$ $P \text{ н.мм} = 360.3$ $P \text{ вн.мм} = 180.1$ Гр. сл. = V Точн. = П </p>		<p>ПЗ-150</p> <p> $F \text{ см}^2 = 1.055$ $Q \text{ кг.} = 0.286$ $D \text{ оп.мм} = 25.9$ $P \text{ н.мм} = 95.0$ $P \text{ вн.мм} = 45.8$ Гр. сл. = IV Точн. = П </p>

	<p>ПЗ-151</p> <p> $F \text{ см}^2 = 2.401$ $Q \text{ кг.} = 0.651$ $D \text{ оп.мм} = 50.0$ $P \text{ н.мм} = 196.7$ $P \text{ вн.мм} = 93.2$ Гр. сл. = V Точн. = П </p>		<p>ПЗ-156</p> <p> $F \text{ см}^2 = 2.860$ $Q \text{ кг.} = 0.775$ $D \text{ оп.мм} = 77.5$ $P \text{ н.мм} = 231.0$ $P \text{ вн.мм} = 89.8$ Гр. сл. = V Точн. = П </p>
	<p>ПЗ-152</p> <p> $F \text{ см}^2 = 3.158$ $Q \text{ кг.} = 0.856$ $D \text{ оп.мм} = 90.1$ $P \text{ н.мм} = 290.3$ $P \text{ вн.мм} = 79.1$ Гр. сл. = V Точн. = П </p>		<p>ПЗ-157</p> <p> $F \text{ см}^2 = 2.110$ $Q \text{ кг.} = 0.572$ $D \text{ оп.мм} = 42.0$ $P \text{ н.мм} = 179.3$ $P \text{ вн.мм} = 87.3$ Гр. сл. = V Точн. = П </p>
	<p>ПЗ-153</p> <p> $F \text{ см}^2 = 6.698$ $Q \text{ кг.} = 1.815$ $D \text{ оп.мм} = 105.2$ $P \text{ н.мм} = 430.3$ $P \text{ вн.мм} = 249.1$ Гр. сл. = VI Точн. = П </p>		<p>ПЗ-158</p> <p> $F \text{ см}^2 = 2.471$ $Q \text{ кг.} = 0.670$ $D \text{ оп.мм} = 43.1$ $P \text{ н.мм} = 273.4$ $P \text{ вн.мм} = 69.8$ Гр. сл. = 0соб. Точн. = П </p>
	<p>ПЗ-154</p> <p> $F \text{ см}^2 = 2.603$ $Q \text{ кг.} = 0.705$ $D \text{ оп.мм} = 54.9$ $P \text{ н.мм} = 204.9$ $P \text{ вн.мм} = 105.4$ Гр. сл. = V Точн. = П </p>		<p>ПЗ-159</p> <p> $F \text{ см}^2 = 1.541$ $Q \text{ кг.} = 0.418$ $D \text{ оп.мм} = 35.0$ $P \text{ н.мм} = 178.4$ $P \text{ вн.мм} = 75.5$ Гр. сл. = 0соб. Точн. = П </p>
	<p>ПЗ-155</p> <p> $F \text{ см}^2 = 2.802$ $Q \text{ кг.} = 0.759$ $D \text{ оп.мм} = 68.8$ $P \text{ н.мм} = 213.8$ $P \text{ вн.мм} = 101.1$ Гр. сл. = V Точн. = П </p>		<p>ПЗ-160</p> <p> $F \text{ см}^2 = 2.010$ $Q \text{ кг.} = 0.545$ $D \text{ оп.мм} = 48.0$ $P \text{ н.мм} = 163.7$ $P \text{ вн.мм} = 178.5$ Гр. сл. = 0соб. Точн. = П </p>

	<p>ПЗ-161</p> <p> $F \text{ см}^2 = 1.543$ $Q \text{ кг.} = 0.418$ $D \text{ оп.мм} = 41.0$ $P \text{ н.мм} = 149.4$ $P \text{ вн.мм} = 87.2$ Гр. сл. = VI Точн. = П </p>		<p>ПЗ-166</p> <p> $F \text{ см}^2 = 1.589$ $Q \text{ кг.} = 0.431$ $D \text{ оп.мм} = 34.4$ $P \text{ н.мм} = 138.0$ $P \text{ вн.мм} = 61.0$ Гр. сл. = V Точн. = П </p>
	<p>ПЗ-162</p> <p> $F \text{ см}^2 = 2.106$ $Q \text{ кг.} = 0.571$ $D \text{ оп.мм} = 44.0$ $P \text{ н.мм} = 197.0$ $P \text{ вн.мм} = 68.0$ Гр. сл. = V Точн. = П </p>		<p>ПЗ-167</p> <p> $F \text{ см}^2 = 1.988$ $Q \text{ кг.} = 0.539$ $D \text{ оп.мм} = 41.0$ $P \text{ н.мм} = 180.0$ $P \text{ вн.мм} = 68.0$ Гр. сл. = V Точн. = П </p>
	<p>ПЗ-163</p> <p> $F \text{ см}^2 = 1.572$ $Q \text{ кг.} = 0.426$ $D \text{ оп.мм} = 35.0$ $P \text{ н.мм} = 144.0$ $P \text{ вн.мм} = 59.0$ Гр. сл. = V Точн. = П </p>		
	<p>ПЗ-164</p> <p> $F \text{ см}^2 = 2.343$ $Q \text{ кг.} = 0.635$ $D \text{ оп.мм} = 52.6$ $P \text{ н.мм} = 189.0$ $P \text{ вн.мм} = 106.0$ Гр. сл. = V Точн. = П </p>		
	<p>ПЗ-165</p> <p> $F \text{ см}^2 = 2.151$ $Q \text{ кг.} = 0.583$ $D \text{ оп.мм} = 50.7$ $P \text{ н.мм} = 180.0$ $P \text{ вн.мм} = 95.0$ Гр. сл. = V Точн. = П </p>		