









































	OK-1	(ПОСТ-23)	OK-6
	$F \text{ см}^2 = 5,44$ $Q \text{ кг} = 1,474$ $D \text{ оп.мм} = 107,7$ $P \text{ н.мм} = 280$ Гр. сл. = III Точн. = Н		$F \text{ см}^2 = 2,42$ $Q \text{ кг} = 0,656$ $D \text{ оп.мм} = 38,2$ $P \text{ н.мм} = 168,3$ Гр. сл. = V Точн. = Н
	OK-2	(ПОСТ-22)	OK-7
	$F \text{ см}^2 = 6,24$ $Q \text{ кг} = 1,691$ $D \text{ оп.мм} = 126,5$ $P \text{ н.мм} = 320$ Гр. сл. = III Точн. = Н		$F \text{ см}^2 = 4,269$ $Q \text{ кг} = 1,157$ $D \text{ оп.мм} = 60,2$ $P \text{ н.мм} = 224,2$ Гр. сл. = VI Точн. = Н
	OK-3		OK-8
	$F \text{ см}^2 = 3,84$ $Q \text{ кг} = 1,041$ $D \text{ оп.мм} = 72,1$ $P \text{ н.мм} = 200$ Гр. сл. = III Точн. = Н		$F \text{ см}^2 = 0,463$ $Q \text{ кг} = 0,125$ $D \text{ оп.мм} = 30$ $P \text{ н.мм} = 63,2$ Гр. сл. = IV Точн. = Н
	OK-4		OK-9
	$F \text{ см}^2 = 0,6248$ $Q \text{ кг} = 0,1693$ $D \text{ оп.мм} = 34,9$ $P \text{ н.мм} = 93,95$ Гр. сл. = V Точн. = Н		$F \text{ см}^2 = 0,408$ $Q \text{ кг} = 0,111$ $D \text{ оп.мм} = 26$ $P \text{ н.мм} = 56,7$ Гр. сл. = IV Точн. = Н
	OK-5		OK-10
	$F \text{ см}^2 = 0,791$ $Q \text{ кг} = 0,215$ $D \text{ оп.мм} = 37,1$ $P \text{ н.мм} = 133,7$ Гр. сл. = V Точн. = Н		$F \text{ см}^2 = 6,81$ $Q \text{ кг} = 1,846$ $D \text{ оп.мм} = 149,5$ $P \text{ н.мм} = 590$ Гр. сл. = VII Точн. = Н

	<p>OK-11</p> <p> $F \text{ см}^2 = 1.9$ $Q \text{ кг} = 0.515$ $D \text{ оп.мм} = 61$ $P \text{ н.мм} = 186.5$ $\Gamma \text{ р. сл.} = V$ $\text{Точн.} = H$ </p>		<p>OK-16</p> <p> $F \text{ см}^2 = 3.7$ $Q \text{ кг} = 1.002$ $D \text{ оп.мм} = 51$ $P \text{ н.мм} = 222$ $\Gamma \text{ р. сл.} = V$ $\text{Точн.} = H$ </p>
	<p>OK-12</p> <p> $F \text{ см}^2 = 9.07$ $Q \text{ кг} = 2.46$ $D \text{ оп.мм} = 183$ $P \text{ н.мм} = 737$ $\Gamma \text{ р. сл.} = VII$ $\text{Точн.} = H$ </p>		<p>OK-17</p> <p> $F \text{ см}^2 = 18.32$ $Q \text{ кг} = 4.96$ $D \text{ оп.мм} = 186$ $P \text{ н.мм} = 514.6$ $\Gamma \text{ р. сл.} = V$ $\text{Точн.} = П$ </p>
	<p>OK-13</p> <p> $F \text{ см}^2 = 4.28$ $Q \text{ кг} = 1.16$ $D \text{ оп.мм} = 63.6$ $P \text{ н.мм} = 175.7$ $\Gamma \text{ р. сл.} = II$ $\text{Точн.} = H$ </p>		<p>OK-18</p> <p> $F \text{ см}^2 = 7.074$ $Q \text{ кг} = 2.088$ $D \text{ оп.мм} = 124$ $P \text{ н.мм} = 371.1$ $\Gamma \text{ р. сл.} = IV$ $\text{Точн.} = П$ </p>
	<p>OK-14</p> <p> $F \text{ см}^2 = 1.72$ $Q \text{ кг} = 0.466$ $D \text{ оп.мм} = 42.4$ $P \text{ н.мм} = 117.4$ $\Gamma \text{ р. сл.} = II$ $\text{Точн.} = H$ </p>		<p>OK-19</p> <p> $F \text{ см}^2 = 3.984$ $Q \text{ кг} = 1.08$ $D \text{ оп.мм} = 107$ $P \text{ н.мм} = 331$ $\Gamma \text{ р. сл.} = IV$ $\text{Точн.} = П$ </p>
	<p>OK-15</p> <p> $F \text{ см}^2 = 1.3$ $Q \text{ кг} = 0.352$ $D \text{ оп.мм} = 52$ $P \text{ н.мм} = 161$ $\Gamma \text{ р. сл.} = IV$ $\text{Точн.} = П$ </p>		<p>OK-20</p> <p> $F \text{ см}^2 = 0.865$ $Q \text{ кг} = 0.234$ $D \text{ оп.мм} = 31.4$ $P \text{ н.мм} = 71.7$ $\Gamma \text{ р. сл.} = III$ $\text{Точн.} = H$ </p>











	OK-21	(801008)	OK-26
	$F \text{ см}^2 = 4,574$ $Q \text{ кг} = 1,24$ $D \text{ оп.мм} = 53,3$ $P \text{ н.мм} = 424,8$ Гр. сл. = VII Точн. = Н		$F \text{ см}^2 = 1,249$ $Q \text{ кг} = 0,338$ $D \text{ оп.мм} = 52,2$ $P \text{ н.мм} = 208,2$ Гр. сл. = ОСОБ. Точн. = П
(100023)	OK-22	(801009)	OK-27
	$F \text{ см}^2 = 2,13$ $Q \text{ кг} = 0,577$ $D \text{ оп.мм} = 50,2$ $P \text{ н.мм} = 212,6$ Гр. сл. = V Точн. = П		$F \text{ см}^2 = 2,803$ $Q \text{ кг} = 0,76$ $D \text{ оп.мм} = 100,5$ $P \text{ н.мм} = 415,3$ Гр. сл. = ОСОБ. Точн. = П
(100024)	OK-23	(801010)	OK-28
	$F \text{ см}^2 = 3,467$ $Q \text{ кг} = 0,94$ $D \text{ оп.мм} = 51,8$ $P \text{ н.мм} = 317,2$ Гр. сл. = V Точн. = П		$F \text{ см}^2 = 1,582$ $Q \text{ кг} = 0,429$ $D \text{ оп.мм} = 66,5$ $P \text{ н.мм} = 261,5$ Гр. сл. = ОСОБ. Точн. = П
(100055)	OK-24	(ЯВ45.85050х)	OK-29
	$F \text{ см}^2 = 1,585$ $Q \text{ кг} = 0,43$ $D \text{ оп.мм} = 48$ $P \text{ н.мм} = 164,7$ Гр. сл. = V Точн. = П		$F \text{ см}^2 = 1,967$ $Q \text{ кг} = 0,533$ $D \text{ оп.мм} = 50$ $P \text{ н.мм} = 179,5$ Гр. сл. = VI Точн. = Н
(100056XX)	OK-25	(ЯВ-3)	OK-30
	$F \text{ см}^2 = 1,648$ $Q \text{ кг} = 0,446$ $D \text{ оп.мм} = 50$ $P \text{ н.мм} = 127$ Гр. сл. = IV Точн. = П		$F \text{ см}^2 = 13$ $Q \text{ кг} = 3,523$ $D \text{ оп.мм} = 102$ $P \text{ н.мм} = 444,3$ Гр. сл. = V Точн. = Н











(ЯВ-4)	<div data-bbox="248 179 819 431"> </div>	<div data-bbox="891 28 1075 95"> <p>ПК-31</p> </div> <div data-bbox="869 134 1115 532"> <p> $F \text{ см}^2 = 14,77$ $Q \text{ кг} = 4$ $D \text{ оп.мм} = 180$ $P \text{ н.мм} = 458,5$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = Н$ </p> </div>	<div data-bbox="1263 28 1637 95"> <p>(Р96.001-134.60227)</p> </div> <div data-bbox="1211 179 1644 487"> </div>	<div data-bbox="1787 28 1984 95"> <p>ПК-36</p> </div> <div data-bbox="1765 134 2011 532"> <p> $F \text{ см}^2 = 6,591$ $Q \text{ кг} = 1,786$ $D \text{ оп.мм} = 38$ $P \text{ н.мм} = 105,3$ $\Gamma \text{р. сл.} = I$ $\text{Точн.} = Н$ </p> </div>
(ЯВ-5)	<div data-bbox="333 767 748 1007"> </div>	<div data-bbox="891 588 1088 655"> <p>ПК-32</p> </div> <div data-bbox="869 694 1104 1092"> <p> $F \text{ см}^2 = 1,923$ $Q \text{ кг} = 0,521$ $D \text{ оп.мм} = 31$ $P \text{ н.мм} = 82,2$ $\Gamma \text{р. сл.} = III$ $\text{Точн.} = Н$ </p> </div>	<div data-bbox="1323 588 1518 655"> <p>(РОСТ-01)</p> </div> <div data-bbox="1218 711 1568 1047"> </div>	<div data-bbox="1787 588 1984 655"> <p>ПК-37</p> </div> <div data-bbox="1765 694 2011 1092"> <p> $F \text{ см}^2 = 6,734$ $Q \text{ кг} = 1,825$ $D \text{ оп.мм} = 52$ $P \text{ н.мм} = 144,3$ $\Gamma \text{р. сл.} = III$ $\text{Точн.} = П$ </p> </div>
(Г96.002-222.60.207)	<div data-bbox="349 1316 694 1612"> </div>	<div data-bbox="891 1148 1088 1215"> <p>ПК-33</p> </div> <div data-bbox="869 1254 1099 1652"> <p> $F \text{ см}^2 = 5,66$ $Q \text{ кг} = 1,534$ $D \text{ оп.мм} = 28$ $P \text{ н.мм} = 92,4$ $\Gamma \text{р. сл.} = II$ $\text{Точн.} = Н$ </p> </div>	<div data-bbox="1323 1148 1518 1215"> <p>(РОСТ-02)</p> </div> <div data-bbox="1285 1383 1673 1612"> </div>	<div data-bbox="1787 1148 1984 1215"> <p>ПК-38</p> </div> <div data-bbox="1765 1254 2007 1652"> <p> $F \text{ см}^2 = 3,051$ $Q \text{ кг} = 0,827$ $D \text{ оп.мм} = 28$ $P \text{ н.мм} = 69,7$ $\Gamma \text{р. сл.} = III$ $\text{Точн.} = Н$ </p> </div>
(Г96.002-222.60.214)	<div data-bbox="376 1836 703 2189"> </div>	<div data-bbox="891 1708 1088 1775"> <p>ПК-34</p> </div> <div data-bbox="869 1814 1111 2212"> <p> $F \text{ см}^2 = 5,576$ $Q \text{ кг} = 1,511$ $D \text{ оп.мм} = 29$ $P \text{ н.мм} = 91,5$ $\Gamma \text{р. сл.} = II$ $\text{Точн.} = Н$ </p> </div>	<div data-bbox="1308 1708 1509 1775"> <p>(РОСТ-03)</p> </div> <div data-bbox="1200 1892 1621 2189"> </div>	<div data-bbox="1787 1708 1984 1775"> <p>ПК-39</p> </div> <div data-bbox="1765 1814 2011 2212"> <p> $F \text{ см}^2 = 1,398$ $Q \text{ кг} = 0,379$ $D \text{ оп.мм} = 36$ $P \text{ н.мм} = 137,4$ $\Gamma \text{р. сл.} = IV$ $\text{Точн.} = Н$ </p> </div>
(Г96.002-222.60.215)	<div data-bbox="367 2419 707 2682"> </div>	<div data-bbox="891 2268 1088 2335"> <p>ПК-35</p> </div> <div data-bbox="869 2374 1111 2772"> <p> $F \text{ см}^2 = 12,56$ $Q \text{ кг} = 3,404$ $D \text{ оп.мм} = 40$ $P \text{ н.мм} = 125,7$ $\Gamma \text{р. сл.} = I$ $\text{Точн.} = Н$ </p> </div>	<div data-bbox="1308 2268 1509 2335"> <p>(РОСТ-04)</p> </div> <div data-bbox="1200 2447 1657 2710"> </div>	<div data-bbox="1787 2268 1984 2335"> <p>ПК-40</p> </div> <div data-bbox="1765 2374 2011 2772"> <p> $F \text{ см}^2 = 1,498$ $Q \text{ кг} = 0,406$ $D \text{ оп.мм} = 43$ $P \text{ н.мм} = 147,4$ $\Gamma \text{р. сл.} = IV$ $\text{Точн.} = Н$ </p> </div>











(РОСТ-05)	OK-41	(РОСТ-11)	OK-46
	$F \text{ см}^2 = 2,721$ $Q \text{ кг} = 0,737$ $D \text{ оп.мм} = 40$ $P \text{ н.мм} = 101,4$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{Н}$		$F \text{ см}^2 = 0,72$ $Q \text{ кг} = 0,195$ $D \text{ оп.мм} = 31$ $P \text{ н.мм} = 76$ $\Gamma \text{р. сл.} = \text{II}$ $\text{Точн.} = \text{Н}$
(РОСТ-06)	OK-42	(РОСТ-12)	OK-47
	$F \text{ см}^2 = 3,57$ $Q \text{ кг} = 0,967$ $D \text{ оп.мм} = 27$ $P \text{ н.мм} = 73,1$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{Н}$		$F \text{ см}^2 = 0,52$ $Q \text{ кг} = 0,141$ $D \text{ оп.мм} = 21,5$ $P \text{ н.мм} = 56$ $\Gamma \text{р. сл.} = \text{II}$ $\text{Точн.} = \text{Н}$
(РОСТ-07)	OK-43	(РОСТ-17)	OK-48
	$F \text{ см}^2 = 1,17$ $Q \text{ кг} = 0,317$ $D \text{ оп.мм} = 31,6$ $P \text{ н.мм} = 102$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{Н}$		$F \text{ см}^2 = 1,416$ $Q \text{ кг} = 0,384$ $D \text{ оп.мм} = 31$ $P \text{ н.мм} = 105,5$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{Н}$
(РОСТ-08)	OK-44	(РОСТ-18)	OK-49
	$F \text{ см}^2 = 2,671$ $Q \text{ кг} = 0,734$ $D \text{ оп.мм} = 57$ $P \text{ н.мм} = 194,1$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \text{П}$		$F \text{ см}^2 = 2,393$ $Q \text{ кг} = 0,649$ $D \text{ оп.мм} = 36$ $P \text{ н.мм} = 159,8$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \text{Н}$
(РОСТ-9)	OK-45	(РДГ-180)	OK-50
	$F \text{ см}^2 = 1,999$ $Q \text{ кг} = 0,542$ $D \text{ оп.мм} = 39$ $P \text{ н.мм} = 141,6$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{П}$		$F \text{ см}^2 = 7,308$ $Q \text{ кг} = 1,98$ $D \text{ оп.мм} = 181$ $P \text{ н.мм} = 705,6$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \text{П}$











(Г-130)	OK-51		OK-56
	$F \text{ см}^2 = 7,425$ $Q \text{ кг} = 2,12$ $D \text{ оп.мм} = 154$ $P \text{ н.мм} = 463,3$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = П$		$F \text{ см}^2 = 3,437$ $Q \text{ кг} = 0,932$ $D \text{ оп.мм} = 51$ $P \text{ н.мм} = 211,1$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = П$
(Т-2)	OK-52		OK-57
	$F \text{ см}^2 = 0,781$ $Q \text{ кг} = 0,212$ $D \text{ оп.мм} = 29$ $P \text{ н.мм} = 104,1$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = П$		$F \text{ см}^2 = 2,05$ $Q \text{ кг} = 0,556$ $D \text{ оп.мм} = 62,4$ $P \text{ н.мм} = 210$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = Н$
	OK-53		OK-58
	$F \text{ см}^2 = 1,76$ $Q \text{ кг} = 0,477$ $D \text{ оп.мм} = 64$ $P \text{ н.мм} = 180$ $\Gamma \text{р. сл.} = IV$ $\text{Точн.} = Н$		$F \text{ см}^2 = 1,78$ $Q \text{ кг} = 0,485$ $D \text{ оп.мм} = 64$ $P \text{ н.мм} = 187,8$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = Н$
	OK-54	(C1)	OK-59
	$F \text{ см}^2 = 4,64$ $Q \text{ кг} = 1,257$ $D \text{ оп.мм} = 89,4$ $P \text{ н.мм} = 240$ $\Gamma \text{р. сл.} = III$ $\text{Точн.} = Н$		$F \text{ см}^2 = 11,891$ $Q \text{ кг} = 3,222$ $D \text{ оп.мм} = 58$ $P \text{ н.мм} = 256$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = Н$
	OK-55	(C2)	OK-60
	$F \text{ см}^2 = 3,16$ $Q \text{ кг} = 0,856$ $D \text{ оп.мм} = 110,2$ $P \text{ н.мм} = 320$ $\Gamma \text{р.сл.} = VII$ $\text{Точн.} = Н$		$F \text{ см}^2 = 10,54$ $Q \text{ кг} = 2,86$ $D \text{ оп.мм} = 52$ $P \text{ н.мм} = 230,6$ $\Gamma \text{р. сл.} = IV$ $\text{Точн.} = Н$





















(C3)	<div data-bbox="353 210 739 498"> </div>	<div data-bbox="891 28 1075 98"> <p>OK-61</p> </div> <div data-bbox="869 134 1097 532"> <p> $F \text{ см}^2 = 2,58$ $Q \text{ кг} = 0,7$ $D \text{ оп.мм} = 34$ $P \text{ н.мм} = 99$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{Н}$ </p> </div>	<div data-bbox="1198 210 1624 489"> </div>	<div data-bbox="1787 28 1982 98"> <p>OK-66</p> </div> <div data-bbox="1765 134 2004 532"> <p> $F \text{ см}^2 = 1,176$ $Q \text{ кг} = 0,319$ $D \text{ оп.мм} = 32,7$ $P \text{ н.мм} = 85,3$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{Н}$ </p> </div>
(C4)	<div data-bbox="313 742 784 1064"> </div>	<div data-bbox="891 588 1086 658"> <p>OK-62</p> </div> <div data-bbox="869 694 1097 1092"> <p> $F \text{ см}^2 = 3,42$ $Q \text{ кг} = 0,927$ $D \text{ оп.мм} = 36$ $P \text{ н.мм} = 112,4$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{Н}$ </p> </div>	<div data-bbox="1243 770 1624 1007"> </div>	<div data-bbox="1787 588 1982 658"> <p>OK-67</p> </div> <div data-bbox="1765 694 2004 1092"> <p> $F \text{ см}^2 = 0,453$ $Q \text{ кг} = 0,123$ $D \text{ оп.мм} = 28$ $P \text{ н.мм} = 75,25$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \text{Н}$ </p> </div>
	<div data-bbox="280 1344 683 1568"> </div>	<div data-bbox="891 1148 1086 1218"> <p>OK-63</p> </div> <div data-bbox="869 1254 1097 1652"> <p> $F \text{ см}^2 = 0,467$ $Q \text{ кг} = 0,127$ $D \text{ оп.мм} = 29,6$ $P \text{ н.мм} = 67,2$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{Н}$ </p> </div>	<div data-bbox="1176 1246 1657 1638"> </div>	<div data-bbox="1787 1148 1982 1218"> <p>OK-68</p> </div> <div data-bbox="1765 1254 2004 1652"> <p> $F \text{ см}^2 = 22,57$ $Q \text{ кг} = 6,12$ $D \text{ оп.мм} = 112,3$ $P \text{ н.мм} = 367,6$ $\Gamma \text{р. сл.} = \text{III}$ $\text{Точн.} = \text{Н}$ </p> </div>
	<div data-bbox="347 1861 750 2142"> </div>	<div data-bbox="891 1708 1086 1778"> <p>OK-64</p> </div> <div data-bbox="869 1814 1097 2212"> <p> $F \text{ см}^2 = 0,713$ $Q \text{ кг} = 0,193$ $D \text{ оп.мм} = 32,7$ $P \text{ н.мм} = 88,9$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{Н}$ </p> </div>	<div data-bbox="1220 1861 1624 2142"> </div>	<div data-bbox="1787 1708 1982 1778"> <p>OK-69</p> </div> <div data-bbox="1765 1814 2004 2212"> <p> $F \text{ см}^2 = 8,365$ $Q \text{ кг} = 2,27$ $D \text{ оп.мм} = 52,8$ $P \text{ н.мм} = 148,2$ $\Gamma \text{р. сл.} = \text{II}$ $\text{Точн.} = \text{Н}$ </p> </div>
	<div data-bbox="347 2422 761 2716"> </div>	<div data-bbox="891 2268 1086 2338"> <p>OK-65</p> </div> <div data-bbox="869 2374 1097 2772"> <p> $F \text{ см}^2 = 1,01$ $Q \text{ кг} = 0,273$ $D \text{ оп.мм} = 32,7$ $P \text{ н.мм} = 86,4$ $\Gamma \text{р. сл.} = \text{IV}$ $\text{Точн.} = \text{Н}$ </p> </div>	<div data-bbox="1153 2436 1646 2730"> </div>	<div data-bbox="1787 2268 1982 2338"> <p>OK-70</p> </div> <div data-bbox="1765 2374 2004 2772"> <p> $F \text{ см}^2 = 3,673$ $Q \text{ кг} = 0,995$ $D \text{ оп.мм} = 36,6$ $P \text{ н.мм} = 145,1$ $\Gamma \text{р. сл.} = \text{V}$ $\text{Точн.} = \text{Н}$ </p> </div>











	<div data-bbox="891 28 1075 98" data-label="Text"> <p>□К-71</p> </div>		<div data-bbox="1787 28 1971 98" data-label="Text"> <p>□К-76</p> </div>
	<div data-bbox="869 134 1102 532" data-label="Text"> <p> $F \text{ см}^2 = 1.845$ $Q \text{ кг} = 0.5$ $D \text{ оп.мм} = 44.2$ $P \text{ н.мм} = 235$ $\Gamma \text{р. сл.} = VI$ $\text{Точн.} = П$ </p> </div>		<div data-bbox="1765 134 1998 532" data-label="Text"> <p> $F \text{ см}^2 = 2.46$ $Q \text{ кг} = 0.667$ $D \text{ оп.мм} = 98$ $P \text{ н.мм} = 252.6$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = Н$ </p> </div>
	<div data-bbox="891 588 1075 658" data-label="Text"> <p>□К-72</p> </div>		<div data-bbox="1787 588 1971 658" data-label="Text"> <p>□К-77</p> </div>
	<div data-bbox="869 694 1102 1092" data-label="Text"> <p> $F \text{ см}^2 = 5.483$ $Q \text{ кг} = 1.486$ $D \text{ оп.мм} = 118$ $P \text{ н.мм} = 401.4$ $\Gamma \text{р. сл.} = VI$ $\text{Точн.} = П$ </p> </div>		<div data-bbox="1765 694 1998 1092" data-label="Text"> <p> $F \text{ см}^2 = 2.29$ $Q \text{ кг} = 0.621$ $D \text{ оп.мм} = 110$ $P \text{ н.мм} = 265$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = Н$ </p> </div>
	<div data-bbox="891 1148 1075 1218" data-label="Text"> <p>□К-73</p> </div>		<div data-bbox="1787 1148 1971 1218" data-label="Text"> <p>□К-78</p> </div>
	<div data-bbox="869 1254 1102 1652" data-label="Text"> <p> $F \text{ см}^2 = 0.5345$ $Q \text{ кг} = 0.145$ $D \text{ оп.мм} = 22$ $P \text{ н.мм} = 58.65$ $\Gamma \text{р. сл.} = III$ $\text{Точн.} = Н$ </p> </div>		<div data-bbox="1765 1254 1998 1652" data-label="Text"> <p> $F \text{ см}^2 = 9.78$ $Q \text{ кг} = 2.65$ $D \text{ оп.мм} = 147$ $P \text{ н.мм} = 627$ $\Gamma \text{р. сл.} = VII$ $\text{Точн.} = Н$ </p> </div>
	<div data-bbox="891 1708 1075 1778" data-label="Text"> <p>□К-74</p> </div>		<div data-bbox="1787 1708 1971 1778" data-label="Text"> <p>□К-79</p> </div>
	<div data-bbox="869 1814 1102 2212" data-label="Text"> <p> $F \text{ см}^2 = 3.661$ $Q \text{ кг} = 0.992$ $D \text{ оп.мм} = 56.5$ $P \text{ н.мм} = 260.6$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = П$ </p> </div>		<div data-bbox="1765 1814 1998 2212" data-label="Text"> <p> $F \text{ см}^2 = 0.7062$ $Q \text{ кг} = 0.1914$ $D \text{ оп.мм} = 17.52$ $P \text{ н.мм} = 65.79$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = Н$ </p> </div>
	<div data-bbox="891 2268 1075 2338" data-label="Text"> <p>□К-75</p> </div>		<div data-bbox="1787 2268 1971 2338" data-label="Text"> <p>□К-80</p> </div>
	<div data-bbox="869 2374 1102 2772" data-label="Text"> <p> $F \text{ см}^2 = 12.63$ $Q \text{ кг} = 3.43$ $D \text{ оп.мм} = 147.5$ $P \text{ н.мм} = 683.8$ $\Gamma \text{р. сл.} = VII$ $\text{Точн.} = Н$ </p> </div>		<div data-bbox="1765 2374 1998 2772" data-label="Text"> <p> $F \text{ см}^2 = 3.002$ $Q \text{ кг} = 0.814$ $D \text{ оп.мм} = 48.7$ $P \text{ н.мм} = 220.9$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = П$ </p> </div>











	<p>ОК-81</p> <p> $F \text{ см}^2 = 8.591$ $Q \text{ кг} = 2.328$ $D \text{ оп.мм} = 133.8$ $P \text{ н.мм} = 442.1$ $\Gamma \text{ р. сл.} = V$ $\text{Точн.} = \Pi$ </p>		<p>ОК-86</p> <p> $F \text{ см}^2 = 6.51$ $Q \text{ кг} = 1.764$ $D \text{ оп.мм} = 144.4$ $P \text{ н.мм} = 511$ $\Gamma \text{ р. сл.} = VI$ $\text{Точн.} = \Pi$ </p>
	<p>ОК-82</p> <p> $F \text{ см}^2 = 6.981$ $Q \text{ кг} = 1.892$ $D \text{ оп.мм} = 105.4$ $P \text{ н.мм} = 372.5$ $\Gamma \text{ р. сл.} = V$ $\text{Точн.} = \Pi$ </p>		<p>ОК-87</p> <p> $F \text{ см}^2 = 1.23$ $Q \text{ кг} = 0.3333$ $D \text{ оп.мм} = 51$ $P \text{ н.мм} = 207.2$ $\Gamma \text{ р. сл.} = V$ $\text{Точн.} = \Pi$ </p>
	<p>ОК-83</p> <p> $F \text{ см}^2 = 2.045$ $Q \text{ кг} = 0.554$ $D \text{ оп.мм} = 61$ $P \text{ н.мм} = 200$ $\Gamma \text{ р. сл.} = V$ $\text{Точн.} = \Pi$ </p>		<p>ОК-88</p> <p> $F \text{ см}^2 = 10.55$ $Q \text{ кг} = 2.86$ $D \text{ оп.мм} = 164.9$ $P \text{ н.мм} = 503$ $\Gamma \text{ р. сл.} = IV$ $\text{Точн.} = \Pi$ </p>
	<p>ОК-84</p> <p> $F \text{ см}^2 = 0.635$ $Q \text{ кг} = 0.1721$ $D \text{ оп.мм} = 40.2$ $P \text{ н.мм} = 87.75$ $\Gamma \text{ р. сл.} = IV$ $\text{Точн.} = H$ </p>		<p>ОК-89</p> <p> $F \text{ см}^2 = 2.238$ $Q \text{ кг} = 0.606$ $D \text{ оп.мм} = 98$ $P \text{ н.мм} = 278$ $\Gamma \text{ р. сл.} = IV$ $\text{Точн.} = \Pi$ </p>
	<p>ОК-85</p> <p> $F \text{ см}^2 = 0.792$ $Q \text{ кг} = 0.2146$ $D \text{ оп.мм} = 40.54$ $P \text{ н.мм} = 102.5$ $\Gamma \text{ р. сл.} = IV$ $\text{Точн.} = H$ </p>		<p>ОК-90</p> <p> $F, \text{ см}^2 = 75.939$ $Q, \text{ кг} = 20.579$ $D \text{ оп.мм} = 192.4$ $P \text{ н.мм} = 2148.53$ $\Gamma \text{ р. сл.} = VII$ $\text{Точн.} = \Pi$ </p>

	<p>ОК-91</p> <p> $F \text{ см}^2=15.885$ $Q \text{ кг} =4.305$ $D \text{ оп.мм}=150$ $P_{н.мм}=743.44$ Гр. сл. = V Точн. = 0сб. </p>		<p>ОК-96</p> <p> $F \text{ см}^2= 2.62$ $Q \text{ кг} = 0.71$ $D \text{ оп.мм}= 80.7$ $P_{н.мм} = 350$ Гр. сл. = V Точн. = П </p>
	<p>ОК-92</p> <p> $F \text{ см}^2= 1.08$ $Q \text{ кг} = 0.293$ $D \text{ оп.мм}=28.8$ $P_{н.мм} =102$ Гр. сл. =VI Точн. = П </p>		<p>ОК-97</p> <p> $F \text{ см}^2= 0.486$ $Q \text{ кг} = 0.132$ $D \text{ оп.мм}=29$ $P_{н.мм} = 61.6$ Гр. сл. = IV Точн. = Н </p>
	<p>ОК-93</p> <p> $F \text{ см}^2= 7.05$ $Q \text{ кг} = 1.91$ $D \text{ оп.мм}=226.2$ $P_{н.мм} =568.9$ Гр. сл. = VII Точн. = П </p>		<p>ОК-98</p> <p> $F, \text{ см}^2 =13.484$ $Q, \text{ кг} = 3.654$ $D \text{ оп.,мм} =72.95$ $P_{н,мм} = 675.85$ Гр. сл. = 0сб. Точн. = Н </p>
	<p>ОК-94</p> <p> $F \text{ см}^2= 58.36$ $Q \text{ кг} = 15.82$ $D \text{ оп.мм}=185.4$ $P_{н.мм} =2473$ Гр. сл. = VII Точн. = П </p>		<p>ОК-99</p> <p> $F, \text{ см}^2 = 11.43$ $Q, \text{ кг} = 3.098$ $D \text{ оп.,мм} = 70$ $P_{н,мм} = 618.7$ Гр. сл. = 0сб. Точн. = Н </p>
	<p>ОК-95</p> <p> $F \text{ см}^2= 2.91$ $Q \text{ кг} = 0.79$ $D \text{ оп.мм}=79$ $P_{н.мм} =318.5$ Гр.сл.= V Точн. = П </p>		<p>ОК-100</p> <p> $F \text{ см}^2= 0.626$ $Q \text{ кг} = 0.167$ $D \text{ оп.мм}= 30$ $P_{н.мм} = 85.1$ Гр. сл. = IV Точн. = Н </p>











	□К-101		□К-106
	$F \text{ см}^2 = 0.6$ $Q \text{ кг} = 0.163$ $D \text{ оп.мм} = 35$ $P \text{ н.мм} = 78.04$ Гр. сл. = IV Точн. = Н		$F \text{ см}^2 = 6$ $Q \text{ кг} = 1.626$ $D \text{ оп.мм} = 61$ $P \text{ н.мм} = 140$ Гр. сл. = I Точн. = Н
	□К-102		□К-107
	$F \text{ см}^2 = 25.3$ $Q \text{ кг} = 6.86$ $D \text{ оп.мм} = 209.2$ $P \text{ н.мм} = 234.85$ Гр. сл. = VII Точн. = Н		$F \text{ см}^2 = 14.82$ $Q \text{ кг} = 4.016$ $D \text{ оп.мм} = 106.6$ $P \text{ н.мм} = 237.4$ Гр. сл. = III Точн. = Н
	□К-103		□К-108
	$F \text{ см}^2 = 1.206$ $Q \text{ кг} = 0.327$ $D \text{ оп.мм} = 49$ $P \text{ н.мм} = 141.5$ Гр. сл. = V Точн. = Н		$F \text{ см}^2 = 26.43$ $Q \text{ кг} = 7.163$ $D \text{ оп.мм} = 116.8$ $P \text{ н.мм} = 273.4$ Гр. сл. = III Точн. = Н
	□К-104		□К-109
	$F \text{ см}^2 = 20.21$ $Q \text{ кг} = 5.477$ $D \text{ оп.мм} = 108.2$ $P \text{ н.мм} = 686.6$ Гр. сл. = VI Точн. = Н		$F \text{ см}^2 = 30.78$ $Q \text{ кг} = 8.341$ $D \text{ оп.мм} = 141.3$ $P \text{ н.мм} = 321.4$ Гр. сл. = III Точн. = Н
	□К-105		□К-110
	$F \text{ см}^2 = 35.495$ $Q \text{ кг} = 9.619$ $D \text{ оп.мм} = 219.3$ $P \text{ н.мм} = 718.35$ Гр. сл. = V Точн. = Н		$F \text{ см}^2 = 24.2$ $Q \text{ кг} = 6.558$ $D \text{ оп.мм} = 70.4$ $P \text{ н.мм} = 198$ Гр. сл. = III Точн. = Н

	ОК-111		ОК-116
	$F \text{ см}^2 = 0,623$ $Q \text{ кг} = 0,169$ $D \text{ оп.мм} = 24,7$ $P \text{ н.мм} = 81,74$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = П$		$F \text{ см}^2 = 1,244$ $Q \text{ кг} = 0,337$ $D \text{ оп.мм} = 28$ $P \text{ н.мм} = 115,64$ $\Gamma \text{р. сл.} = IV$ $\text{Точн.} = П$
	ОК-112		ОК-117
	$F \text{ см}^2 = 0,636$ $Q \text{ кг} = 0,172$ $D \text{ оп.мм} = 27,4$ $P \text{ н.мм} = 81,38$ $\text{ЗБр. сл.} = V$ $\text{Точн.} = П$		$F \text{ см}^2 = 18,711$ $Q \text{ кг} = 5,071$ $D \text{ оп.мм} = 180,3$ $P \text{ н.мм} = 434$ $\Gamma \text{р. сл.} = III$ $\text{Точн.} = Н$
	ОК-113		ОК-118
	$F \text{ см}^2 = 1,112$ $Q \text{ кг} = 0,301$ $D \text{ оп.мм} = 41,8$ $P \text{ н.мм} = 132,22$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = П$		$F \text{ см}^2 = 3,721$ $Q \text{ кг} = 1,008$ $D \text{ оп.мм} = 171$ $P \text{ н.мм} = 378$ $\Gamma \text{р. сл.} = 0 \text{ сб.}$ $\text{Точн.} = Н$
	ОК-114		ОК-119
	$F \text{ см}^2 = 2,334$ $Q \text{ кг} = 0,633$ $D \text{ оп.мм} = 53,81$ $P \text{ н.мм} = 150,75$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = П$		$F \text{ см}^2 = 5,046$ $Q \text{ кг} = 1,367$ $D \text{ оп.мм} = 237,3$ $P \text{ н.мм} = 521$ $\Gamma \text{р. сл.} = 0 \text{ сб.}$ $\text{Точн.} = Н$
	ОК-115		ОК-120
 профиль резьбы М6	$F \text{ см}^2 = 2,196$ $Q \text{ кг} = 0,595$ $D \text{ оп.мм} = 70,3$ $P \text{ н.мм} = 211,38$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = П$		$F \text{ см}^2 = 0,558$ $Q \text{ кг} = 0,151$ $D \text{ оп.мм} = 25,34$ $P \text{ н.мм} = 86,44$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = Н$











	<p>ОК-121</p> <p> $F \text{ см}^2=13,362$ $Q \text{ кг} = 3,621$ $D \text{ оп.мм}=106$ $P \text{ н.мм} =782$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = \square$ </p>		<p>ОК-126</p> <p> $F \text{ см}^2= 2,009$ $Q \text{ кг} = 0,544$ $D \text{ оп.мм}=36,88$ $P \text{ н.мм} =111,2$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = \Pi$ </p>
	<p>ОК-122</p> <p> $F \text{ см}^2=11,798$ $Q \text{ кг} = 3,197$ $D \text{ оп.мм}=56,62$ $P \text{ н.мм} =148,5$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = \square$ </p>		<p>ОК-127</p> <p> $F \text{ см}^2= 3,305$ $Q \text{ кг} = 0,896$ $D \text{ оп.мм}=91,6$ $P \text{ н.мм} = 350$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = H$ </p>
	<p>ОК-123</p> <p> $F \text{ см}^2= 39,66$ $Q \text{ кг} = 10,748$ $D \text{ оп.мм}= 194$ $P \text{ н.мм} = 833$ $\Gamma \text{р. сл.} = IV$ $\text{Точн.} = H$ </p>		<p>ОК-128</p> <p> $F \text{ см}^2= 1,825$ $Q \text{ кг} = 0,495$ $D \text{ оп.мм}= 62$ $P \text{ н.мм} =192,5$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = H$ </p>
	<p>ОК-124</p> <p> $F \text{ см}^2= 15,06$ $Q \text{ кг} = 4,08$ $D \text{ оп.мм}=93,7$ $P \text{ н.мм} =294$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = H$ </p>		<p>ОК-129</p> <p> $F \text{ см}^2 \approx 3,9672$ $Q \text{ кг} = 1,075$ $D \text{ оп.мм}= 126$ $P \text{ н.мм} =331,3$ $\Gamma \text{р. сл.} = \square \text{с}$ $\text{Точн.} = H$ </p>
	<p>ОК-125</p> <p> $F \text{ см}^2= 2,593$ $Q \text{ кг} = 0,703$ $D \text{ оп.мм}=41,49$ $P \text{ н.мм} = 149$ $\Gamma \text{р.сл.}= V$ $\text{Точн.} = \Pi$ </p>		<p>ОК-130</p> <p> $F \text{ см}^2= 2,678$ $Q \text{ кг} = 0,726$ $D \text{ оп.мм}=45,31$ $P \text{ н.мм} =231,3$ $\Gamma \text{р. сл.} =VI$ $\text{Точн.} = \Pi$ </p>











	OK-131		OK-136
	$F \text{ см}^2 = 2,546$ $Q \text{ кг} = 0,69$ $D \text{ оп.мм} = 80,01$ $P \text{ н.мм} = 212$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = П$		$F \text{ см}^2 = 3,536$ $Q \text{ кг} = 0,958$ $D \text{ оп.мм} = 127$ $P \text{ н.мм} = 328$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = П$
	OK-132		OK-137
	$F \text{ см}^2 = 2,404$ $Q \text{ кг} = 0,651$ $D \text{ оп.мм} = 76,15$ $P \text{ н.мм} = 226$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = П$		$F \text{ см}^2 = 8,063$ $Q \text{ кг} = 2,185$ $D \text{ оп.мм} = 160,88$ $P \text{ н.мм} = 740$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = П$
	OK-133		OK-138
	$F \text{ см}^2 = 6,854$ $Q \text{ кг} = 1,857$ $D \text{ оп.мм} = 125$ $P \text{ н.мм} = 356,11$ $\Gamma \text{р. сл.} = IV$ $\text{Точн.} = П$		$F, \text{ см}^2 = 3,581$ $Q, \text{ кг} = 0,97$ $D \text{ оп.мм} = 52$ $P \text{ н.мм} = 181,9$ $\Gamma \text{р. сл.} = III$ $\text{Точн.} = П$
	OK-134		OK-139
	$F \text{ см}^2 = 0,751$ $Q \text{ кг} = 0,204$ $D \text{ оп.мм} = 24,25$ $P \text{ н.мм} = 58,11$ $\Gamma \text{р. сл.} = III$ $\text{Точн.} = П$		$F, \text{ см}^2 = 0,529$ $Q, \text{ кг} = 0,143$ $D \text{ оп.мм} = 22,5$ $P \text{ н.мм} = 52,9$ $\Gamma \text{р. сл.} = II$ $\text{Точн.} = 0 \text{ СОБ}$
	OK-135		OK-140
	$F \text{ см}^2 = 2,829$ $Q \text{ кг} = 0,766$ $D \text{ оп.мм} = 76$ $P \text{ н.мм} = 226,54$ $\Gamma \text{р. сл.} = V$ $\text{Точн.} = П$		$F, \text{ см}^2 = 6,131$ $Q, \text{ кг} = 1,631$ $D \text{ оп.мм} = 89,4$ $P \text{ н.мм} = 307$ $\Gamma \text{р. сл.} = I$ $\text{Точн.} = Н$











	<div data-bbox="891 28 1099 98" data-label="Text"> <p>□К-141</p> </div>		<div data-bbox="1787 28 1995 98" data-label="Text"> <p>□К-146</p> </div>
<div data-bbox="248 170 808 520" data-label="Figure"> </div>	<div data-bbox="860 142 1099 534" data-label="Text"> <p> $F, \text{см}^2 = 4.932$ $Q, \text{кг} = 1.312$ $D_{\text{оп,мм}} = 76.2$ $P_{\text{н,мм}} = 247$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{H}$ </p> </div>	<div data-bbox="1189 212 1671 492" data-label="Figure"> </div>	<div data-bbox="1756 142 1995 534" data-label="Text"> <p> $F, \text{см}^2 = 8.828$ $Q, \text{кг} = 2.392$ $D_{\text{оп,мм}} = 63$ $P_{\text{н,мм}} = 518.8$ $\Gamma_{\text{р. сл.}} = \text{VII}$ $\text{Точн.} = \text{H}$ </p> </div>
	<div data-bbox="891 590 1099 660" data-label="Text"> <p>□К-142</p> </div>		<div data-bbox="1787 590 1995 660" data-label="Text"> <p>□К-147</p> </div>
<div data-bbox="293 744 763 1066" data-label="Figure"> </div>	<div data-bbox="860 702 1099 1094" data-label="Text"> <p> $F, \text{см}^2 = 3.299$ $Q, \text{кг} = 0.878$ $D_{\text{оп,мм}} = 62.6$ $P_{\text{н,мм}} = 220$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{H}$ </p> </div>	<div data-bbox="1144 688 1682 1080" data-label="Figure"> </div>	<div data-bbox="1756 702 1995 1094" data-label="Text"> <p> $F, \text{см}^2 = 3.763$ $Q, \text{кг} = 1.02$ $D_{\text{оп,мм}} = 61$ $P_{\text{н,мм}} = 198.3$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{П}$ </p> </div>
	<div data-bbox="891 1150 1099 1220" data-label="Text"> <p>□К-143</p> </div>		<div data-bbox="1787 1150 1995 1220" data-label="Text"> <p>□К-148</p> </div>
<div data-bbox="248 1304 831 1654" data-label="Figure"> </div>	<div data-bbox="860 1262 1099 1654" data-label="Text"> <p> $F, \text{см}^2 = 2.55$ $Q, \text{кг} = 0.678$ $D_{\text{оп,мм}} = 47.2$ $P_{\text{н,мм}} = 170$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{H}$ </p> </div>	<div data-bbox="1133 1332 1727 1612" data-label="Figure"> </div>	<div data-bbox="1756 1262 1995 1654" data-label="Text"> <p> $F, \text{см}^2 = 1.449$ $Q, \text{кг} = 0.393$ $D_{\text{оп,мм}} = 40.7$ $P_{\text{н,мм}} = 95.57$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{П}$ </p> </div>
	<div data-bbox="891 1710 1099 1780" data-label="Text"> <p>□К-144</p> </div>		<div data-bbox="1787 1710 1995 1780" data-label="Text"> <p>□К-149</p> </div>
<div data-bbox="282 1822 763 2186" data-label="Figure"> </div>	<div data-bbox="860 1822 1099 2214" data-label="Text"> <p> $F, \text{см}^2 = 1.95$ $Q, \text{кг} = 0.519$ $D_{\text{оп,мм}} = 36.1$ $P_{\text{н,мм}} = 130$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{H}$ </p> </div>	<div data-bbox="1167 1850 1693 2144" data-label="Figure"> </div>	<div data-bbox="1756 1822 1995 2214" data-label="Text"> <p> $F, \text{см}^2 = 1.687$ $Q, \text{кг} = 0.457$ $D_{\text{оп,мм}} = 48.77$ $P_{\text{н,мм}} = 109.7$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{П}$ </p> </div>
	<div data-bbox="891 2270 1099 2340" data-label="Text"> <p>□К-145</p> </div>		<div data-bbox="1787 2270 1995 2340" data-label="Text"> <p>□К-150</p> </div>
<div data-bbox="259 2396 808 2760" data-label="Figure"> </div>	<div data-bbox="860 2382 1099 2774" data-label="Text"> <p> $F, \text{см}^2 = 2.849$ $Q, \text{кг} = 0.758$ $D_{\text{оп,мм}} = 55.9$ $P_{\text{н,мм}} = 190.14$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{H}$ </p> </div>	<div data-bbox="1178 2382 1704 2746" data-label="Figure"> </div>	<div data-bbox="1756 2382 1995 2774" data-label="Text"> <p> $F, \text{см}^2 = 3.721$ $Q, \text{кг} = 1.008$ $D_{\text{оп,мм}} = 52.6$ $P_{\text{н,мм}} = 207.7$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{П}$ </p> </div>











	OK-151		OK-156
	$F, \text{ см}^2 = 0,535$ $Q, \text{ кг} = 0,145$ $D_{\text{оп,мм}} = 25,1$ $P_{\text{н,мм}} = 30$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \Pi$		$F, \text{ см}^2 = 4,064$ $Q, \text{ кг} = 1,101$ $D_{\text{оп,мм}} = 132,3$ $P_{\text{н,мм}} = 531,1$ $\Gamma_{\text{р. сл.}} = \text{VI}$ $\text{Точн.} = \text{H}$
	OK-152		OK-157
	$F, \text{ см}^2 = 17,837$ $Q, \text{ кг} = 4,834$ $D_{\text{оп,мм}} = 180,1$ $P_{\text{н,мм}} = 502,6$ $\Gamma_{\text{р. сл.}} = \text{V}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 2,769$ $Q, \text{ кг} = 0,75$ $D_{\text{оп,мм}} = 78,07$ $P_{\text{н,мм}} = 291,4$ $\Gamma_{\text{р. сл.}} = \text{VI}$ $\text{Точн.} = \text{O}$
	OK-153		OK-158
	$F, \text{ см}^2 = 1,25$ $Q, \text{ кг} = 0,339$ $D_{\text{оп,мм}} = 21,54$ $P_{\text{н,мм}} = 86,52$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \Pi$		$F, \text{ см}^2 = 5,289$ $Q, \text{ кг} = 1,433$ $D_{\text{оп,мм}} = 121,26$ $P_{\text{н,мм}} = 475$ $\Gamma_{\text{р. сл.}} = \text{VI}$ $\text{Точн.} = \text{O}$
	OK-154		OK-159
	$F, \text{ см}^2 = 2,099$ $Q, \text{ кг} = 0,558$ $D_{\text{оп,мм}} = 40,3$ $P_{\text{н,мм}} = 140,14$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 6,278$ $Q, \text{ кг} = 1,701$ $D_{\text{оп,мм}} = 92$ $P_{\text{н,мм}} = 336$ $\Gamma_{\text{р. сл.}} = \text{IV}$ $\text{Точн.} = \Pi$
	OK-155		OK-160
	$F, \text{ см}^2 = 2,355$ $Q, \text{ кг} = 0,638$ $D_{\text{оп,мм}} = 68,13$ $P_{\text{н,мм}} = 303,2$ $\Gamma_{\text{р. сл.}} = \text{VI}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 1,014$ $Q, \text{ кг} = 0,275$ $D_{\text{оп,мм}} = 20,2$ $P_{\text{н,мм}} = 92,95$ $\Gamma_{\text{р. сл.}} = \text{VII}$ $\text{Точн.} = \text{H}$











	<div data-bbox="891 28 1102 98" data-label="Text"> <p>□К-161</p> </div>		<div data-bbox="1789 28 2000 98" data-label="Text"> <p>□К-166</p> </div>
<div data-bbox="286 190 779 498" data-label="Figure"> </div>	<div data-bbox="862 142 1108 534" data-label="Text"> <p> $F, \text{ см}^2 = 19,027$ $Q, \text{ кг} = 5,156$ $D_{\text{оп,мм}} = 88,8$ $P_{\text{н,мм}} = 745$ $\Gamma_{\text{р. сл.}} = \text{ОС.}$ $\text{Точн.} = \text{Н}$ </p> </div>	<div data-bbox="1193 148 1686 498" data-label="Figure"> </div>	<div data-bbox="1758 142 2004 534" data-label="Text"> <p> $F, \text{ см}^2 = 1,954$ $Q, \text{ кг} = 0,53$ $D_{\text{оп,мм}} = 47,13$ $P_{\text{н,мм}} = 147,3$ $\Gamma_{\text{р. сл.}} = \text{V}$ $\text{Точн.} = \text{Н}$ </p> </div>
	<div data-bbox="891 590 1102 660" data-label="Text"> <p>□К-162</p> </div>		<div data-bbox="1789 590 2000 660" data-label="Text"> <p>□К-167</p> </div>
<div data-bbox="324 708 763 1100" data-label="Figure"> </div>	<div data-bbox="862 702 1108 1094" data-label="Text"> <p> $F, \text{ см}^2 = 4,52$ $Q, \text{ кг} = 1,225$ $D_{\text{оп,мм}} = 66$ $P_{\text{н,мм}} = 256,4$ $\Gamma_{\text{р. сл.}} = \text{VI}$ $\text{Точн.} = \text{Н}$ </p> </div>	<div data-bbox="1167 708 1653 1100" data-label="Figure"> </div>	<div data-bbox="1758 702 2004 1094" data-label="Text"> <p> $F, \text{ см}^2 = 3,61$ $Q, \text{ кг} = 0,979$ $D_{\text{оп,мм}} = 70$ $P_{\text{н,мм}} = 249$ $\Gamma_{\text{р. сл.}} = \text{V}$ $\text{Точн.} = \text{Н}$ </p> </div>
	<div data-bbox="891 1150 1102 1220" data-label="Text"> <p>□К-163</p> </div>		<div data-bbox="1789 1150 2000 1220" data-label="Text"> <p>□К-168</p> </div>
<div data-bbox="264 1268 801 1660" data-label="Figure"> </div>	<div data-bbox="862 1262 1108 1654" data-label="Text"> <p> $F, \text{ см}^2 = 4,603$ $Q, \text{ кг} = 1,247$ $D_{\text{оп,мм}} = 57$ $P_{\text{н,мм}} = 227,6$ $\Gamma_{\text{р. сл.}} = \text{VI}$ $\text{Точн.} = \text{Н}$ </p> </div>	<div data-bbox="1182 1268 1720 1660" data-label="Figure"> </div>	<div data-bbox="1758 1262 2004 1654" data-label="Text"> <p> $F, \text{ см}^2 = 3,729$ $Q, \text{ кг} = 1,011$ $D_{\text{оп,мм}} = 80,5$ $P_{\text{н,мм}} = 323$ $\Gamma_{\text{р. сл.}} = \text{V}$ $\text{Точн.} = \text{Н}$ </p> </div>
	<div data-bbox="891 1710 1102 1780" data-label="Text"> <p>□К-164</p> </div>		<div data-bbox="1789 1710 2000 1780" data-label="Text"> <p>□К-169</p> </div>
<div data-bbox="264 1884 824 2136" data-label="Figure"> </div>	<div data-bbox="862 1822 1108 2214" data-label="Text"> <p> $F, \text{ см}^2 = 29,497$ $Q, \text{ кг} = 7,994$ $D_{\text{оп,мм}} = 192,4$ $P_{\text{н,мм}} = 2254,6$ $\Gamma_{\text{р. сл.}} = \text{ОСОБ.}$ $\text{Точн.} = \text{Н}$ </p> </div>	<div data-bbox="1182 1856 1675 2192" data-label="Figure"> </div>	<div data-bbox="1758 1822 2004 2214" data-label="Text"> <p> $F, \text{ см}^2 = 11,0$ $Q, \text{ кг} = 2,981$ $D_{\text{оп,мм}} = 100,6$ $P_{\text{н,мм}} = 222$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{Н}$ </p> </div>
	<div data-bbox="891 2270 1102 2340" data-label="Text"> <p>□К-165</p> </div>		<div data-bbox="1789 2270 2000 2340" data-label="Text"> <p>□К-170</p> </div>
<div data-bbox="253 2444 790 2752" data-label="Figure"> </div>	<div data-bbox="862 2382 1108 2774" data-label="Text"> <p> $F, \text{ см}^2 = 7,52$ $Q, \text{ кг} = 2,038$ $D_{\text{оп,мм}} = 59$ $P_{\text{н,мм}} = 217,1$ $\Gamma_{\text{р. сл.}} = \text{VI}$ $\text{Точн.} = \text{П}$ </p> </div>	<div data-bbox="1182 2388 1675 2752" data-label="Figure"> </div>	<div data-bbox="1758 2382 2004 2774" data-label="Text"> <p> $F, \text{ см}^2 = 11,5$ $Q, \text{ кг} = 3,117$ $D_{\text{оп,мм}} = 100,7$ $P_{\text{н,мм}} = 223$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{Н}$ </p> </div>











	□К-171		□К-176
	$F, \text{ см}^2 = 12.0$ $Q, \text{ кг} = 3.252$ $D_{\text{оп.,мм}} = 100.7$ $P_{\text{н.,мм}} = 224$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 14.5$ $Q, \text{ кг} = 3.93$ $D_{\text{оп.,мм}} = 101$ $P_{\text{н.,мм}} = 229$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{H}$
	□К-172		□К-177
	$F, \text{ см}^2 = 12.5$ $Q, \text{ кг} = 3.388$ $D_{\text{оп.,мм}} = 100.8$ $P_{\text{н.,мм}} = 225$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 15.0$ $Q, \text{ кг} = 4.065$ $D_{\text{оп.,мм}} = 101.1$ $P_{\text{н.,мм}} = 230$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{H}$
	□К-173		□К-178
	$F, \text{ см}^2 = 13.0$ $Q, \text{ кг} = 3.523$ $D_{\text{оп.,мм}} = 100.8$ $P_{\text{н.,мм}} = 226$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 15.5$ $Q, \text{ кг} = 4.201$ $D_{\text{оп.,мм}} = 101.2$ $P_{\text{н.,мм}} = 231$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{H}$
	□К-174		□К-179
	$F, \text{ см}^2 = 13.5$ $Q, \text{ кг} = 3.659$ $D_{\text{оп.,мм}} = 100.9$ $P_{\text{н.,мм}} = 227$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 16.0$ $Q, \text{ кг} = 4.336$ $D_{\text{оп.,мм}} = 101.3$ $P_{\text{н.,мм}} = 232$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{H}$
	□К-175		□К-180
	$F, \text{ см}^2 = 14.0$ $Q, \text{ кг} = 3.794$ $D_{\text{оп.,мм}} = 101$ $P_{\text{н.,мм}} = 228$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 16.5$ $Q, \text{ кг} = 4.472$ $D_{\text{оп.,мм}} = 101.4$ $P_{\text{н.,мм}} = 233$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{H}$











	□К-181		□К-186
	$F, \text{ см}^2 = 17.0$ $Q, \text{ кг} = 4.607$ $D_{\text{оп.,мм}} = 101.4$ $P_{\text{н.,мм}} = 234$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 4.95$ $Q, \text{ кг} = 1.341$ $D_{\text{оп.,мм}} = 46.3$ $P_{\text{н.,мм}} = 112$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{H}$
	□К-182		□К-187
	$F, \text{ см}^2 = 17.5$ $Q, \text{ кг} = 4.743$ $D_{\text{оп.,мм}} = 101.5$ $P_{\text{н.,мм}} = 235$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 5.172$ $Q, \text{ кг} = 1.402$ $D_{\text{оп.,мм}} = 46.4$ $P_{\text{н.,мм}} = 113$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{H}$
	□К-183		□К-188
	$F, \text{ см}^2 = 18.0$ $Q, \text{ кг} = 4.878$ $D_{\text{оп.,мм}} = 101.6$ $P_{\text{н.,мм}} = 236$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 5.4$ $Q, \text{ кг} = 1.463$ $D_{\text{оп.,мм}} = 46.6$ $P_{\text{н.,мм}} = 114$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{H}$
	□К-184		□К-189
	$F, \text{ см}^2 = 18.5$ $Q, \text{ кг} = 5.014$ $D_{\text{оп.,мм}} = 101.7$ $P_{\text{н.,мм}} = 237$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 5.625$ $Q, \text{ кг} = 1.524$ $D_{\text{оп.,мм}} = 46.7$ $P_{\text{н.,мм}} = 115$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{H}$
	□К-185		□К-190
	$F, \text{ см}^2 = 19.0$ $Q, \text{ кг} = 5.149$ $D_{\text{оп.,мм}} = 101.8$ $P_{\text{н.,мм}} = 238$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 5.85$ $Q, \text{ кг} = 1.585$ $D_{\text{оп.,мм}} = 46.8$ $P_{\text{н.,мм}} = 116$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{H}$











	□К-191		□К-196
	$F, \text{ см}^2 = 6.075$ $Q, \text{ кг} = 1.646$ $D_{\text{оп.,мм}} = 47$ $P_{\text{н.,мм}} = 117$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 7.2$ $Q, \text{ кг} = 1.951$ $D_{\text{оп.,мм}} = 47.8$ $P_{\text{н.,мм}} = 122$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{H}$
	□К-192		□К-197
	$F, \text{ см}^2 = 6.3$ $Q, \text{ кг} = 1.707$ $D_{\text{оп.,мм}} = 47.1$ $P_{\text{н.,мм}} = 118$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 7.425$ $Q, \text{ кг} = 2.012$ $D_{\text{оп.,мм}} = 48$ $P_{\text{н.,мм}} = 123$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{H}$
	□К-193		□К-198
	$F, \text{ см}^2 = 6.525$ $Q, \text{ кг} = 1.768$ $D_{\text{оп.,мм}} = 47.3$ $P_{\text{н.,мм}} = 119$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 7.65$ $Q, \text{ кг} = 2.073$ $D_{\text{оп.,мм}} = 48.1$ $P_{\text{н.,мм}} = 124$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{H}$
	□К-194		□К-199
	$F, \text{ см}^2 = 6.75$ $Q, \text{ кг} = 1.829$ $D_{\text{оп.,мм}} = 47.4$ $P_{\text{н.,мм}} = 120$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 7.875$ $Q, \text{ кг} = 2.134$ $D_{\text{оп.,мм}} = 48.3$ $P_{\text{н.,мм}} = 125$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{H}$
	□К-195		□К-200
	$F, \text{ см}^2 = 6.975$ $Q, \text{ кг} = 1.89$ $D_{\text{оп.,мм}} = 47.6$ $P_{\text{н.,мм}} = 121$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 8.1$ $Q, \text{ кг} = 2.195$ $D_{\text{оп.,мм}} = 48.5$ $P_{\text{н.,мм}} = 126$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{H}$











	<p>□К-201</p>		<p>□К-206</p>
	<p> $F, \text{см}^2 = 8.325$ $Q, \text{кг} = 2.256$ $D_{\text{оп,мм}} = 48.7$ $P_{\text{н,мм}} = 127$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{H}$ </p>		<p> $F, \text{см}^2 = 3.049$ $Q, \text{кг} = 0.826$ $D_{\text{оп,мм}} = 45.2$ $P_{\text{н,мм}} = 187$ $\Gamma_{\text{р. сл.}} = \text{V II}$ $\text{Точн.} = \text{П}$ </p>
	<p>□К-202</p>		<p>□К-207</p>
	<p> $F, \text{см}^2 = 8.55$ $Q, \text{кг} = 2.317$ $D_{\text{оп,мм}} = 48.8$ $P_{\text{н,мм}} = 128$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{H}$ </p>		<p> $F, \text{см}^2 = 8.773$ $Q, \text{кг} = 2.377$ $D_{\text{оп,мм}} = 143.5$ $P_{\text{н,мм}} = 473.9$ $\Gamma_{\text{р. сл.}} = \text{V}$ $\text{Точн.} = \text{H}$ </p>
	<p>□К-203</p>		<p>□К-208</p>
	<p> $F, \text{см}^2 = 48.64$ $Q, \text{кг} = 13.18$ $D_{\text{оп,мм}} = 133.5$ $P_{\text{н,мм}} = 332$ $\Gamma_{\text{р. сл.}} = \text{I}$ $\text{Точн.} = \text{H}$ </p>		<p> $F, \text{см}^2 = 3.763$ $Q, \text{кг} = 1.02$ $D_{\text{оп,мм}} = 136.7$ $P_{\text{н,мм}} = 382.1$ $\Gamma_{\text{р. сл.}} = \text{V}$ $\text{Точн.} = \text{H}$ </p>
	<p>□К-204</p>		<p>□К-209</p>
	<p> $F, \text{см}^2 = 57.243$ $Q, \text{кг} = 15.513$ $D_{\text{оп,мм}} = 187.8$ $P_{\text{н,мм}} = 2187$ $\Gamma_{\text{р. сл.}} = \text{O C.}$ $\text{Точн.} = \text{П}$ </p>		<p> $F, \text{см}^2 = 9.523$ $Q, \text{кг} = 2.581$ $D_{\text{оп,мм}} = 177$ $P_{\text{н,мм}} = 629.2$ $\Gamma_{\text{р. сл.}} = \text{O C.}$ $\text{Точн.} = \text{H}$ </p>
	<p>□К-205</p>		<p>□К-210</p>
	<p> $F, \text{см}^2 = 0.696$ $Q, \text{кг} = 0.189$ $D_{\text{оп,мм}} = 29.1$ $P_{\text{н,мм}} = 66.4$ $\Gamma_{\text{р. сл.}} = \text{I V}$ $\text{Точн.} = \text{П}$ </p>		<p> $F, \text{см}^2 = 0.861$ $Q, \text{кг} = 0.233$ $D_{\text{оп,мм}} = 49$ $P_{\text{н,мм}} = 137.6$ $\Gamma_{\text{р. сл.}} = \text{V I}$ $\text{Точн.} = \text{П}$ </p>











	<p>ОК-211</p> <p>$F, \text{см}^2 = 4.75$ $Q, \text{кг} = 1.29$ $D_{\text{оп,мм}} = 46$ $P_{\text{н,мм}} = 133.2$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \Pi$</p>		<p>ОК-216</p> <p>$F, \text{см}^2 = 1.401$ $Q, \text{кг} = 0.38$ $D_{\text{оп,мм}} = 47.7$ $P_{\text{н,мм}} = 165.6$ $\Gamma_{\text{р. сл.}} = \vee$ $\text{Точн.} = \square \text{с.}$</p>
	<p>ОК-212</p> <p>$F, \text{см}^2 = 3.296$ $Q, \text{кг} = 0.893$ $D_{\text{оп,мм}} = 38$ $P_{\text{н,мм}} = 111.3$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \Pi$</p>		<p>ОК-217</p> <p>$F, \text{см}^2 = 2.121$ $Q, \text{кг} = 0.575$ $D_{\text{оп,мм}} = 58.8$ $P_{\text{н,мм}} = 216.9$ $\Gamma_{\text{р. сл.}} = \vee$ $\text{Точн.} = \text{H}$</p>
	<p>ОК-213</p> <p>$F, \text{см}^2 = 3.77$ $Q, \text{кг} = 1.02$ $D_{\text{оп,мм}} = 58$ $P_{\text{н,мм}} = 191.4$ $\Gamma_{\text{р. сл.}} = \vee$ $\text{Точн.} = \Pi$</p>		<p>ОК-218</p> <p>$F, \text{см}^2 = 1.484$ $Q, \text{кг} = 0.402$ $D_{\text{оп,мм}} = 41.7$ $P_{\text{н,мм}} = 151.4$ $\Gamma_{\text{р. сл.}} = \vee$ $\text{Точн.} = \text{H}$</p>
	<p>ОК-214</p> <p>$F, \text{см}^2 = 5.709$ $Q, \text{кг} = 1.547$ $D_{\text{оп,мм}} = 164$ $P_{\text{н,мм}} = 570$ $\Gamma_{\text{р. сл.}} = \text{IV}$ $\text{Точн.} = \text{H}$</p>		<p>ОК-219</p> <p>$F, \text{см}^2 = 3.415$ $Q, \text{кг} = 0.925$ $D_{\text{оп,мм}} = 74.4$ $P_{\text{н,мм}} = 307$ $\Gamma_{\text{р. сл.}} = \square \text{с.}$ $\text{Точн.} = \text{H}$</p>
	<p>ОК-215</p> <p>$F, \text{см}^2 = 32.17$ $Q, \text{кг} = 8.718$ $D_{\text{оп,мм}} = 109$ $P_{\text{н,мм}} = 1482$ $\Gamma_{\text{р. сл.}} = \vee \text{II}$ $\text{Точн.} = \text{H}$</p>		<p>ОК-220</p> <p>$F, \text{см}^2 = 2.763$ $Q, \text{кг} = 0.749$ $D_{\text{оп,мм}} = 101.5$ $P_{\text{н,мм}} = 429$ $\Gamma_{\text{р. сл.}} = \vee \text{I}$ $\text{Точн.} = \text{H}$</p>










	ОК-221 $F, \text{ см}^2 = 2.437$ $Q, \text{ кг} = 0.661$ $D_{\text{оп, мм}} = 86.3$ $P_{\text{н, мм}} = 373.6$ Гр. сл. = V I Точн. = Н		ОК-226 $F, \text{ см}^2 = 1.404$ $Q, \text{ кг} = 0.38$ $D_{\text{оп, мм}} = 32.14$ $P_{\text{н, мм}} = 91.05$ Гр. сл. = I I I Точн. = Н
	ОК-222 $F, \text{ см}^2 = 1.833$ $Q, \text{ кг} = 0.497$ $D_{\text{оп, мм}} = 71.3$ $P_{\text{н, мм}} = 251.8$ Гр. сл. = V I Точн. = Н		ОК-227 $F, \text{ см}^2 = 26.101$ $Q, \text{ кг} = 7.073$ $D_{\text{оп, мм}} = 182.25$ $P_{\text{н, мм}} = 928.43$ Гр. сл. = V I Точн. = Н
	ОК-223 $F, \text{ см}^2 = 5.715$ $Q, \text{ кг} = 1.548$ $D_{\text{оп, мм}} = 118.7$ $P_{\text{н, мм}} = 525.1$ Гр. сл. = V I Точн. = Н		ОК-228 $F, \text{ см}^2 = 19.523$ $Q, \text{ кг} = 5.291$ $D_{\text{оп, мм}} = 150.23$ $P_{\text{н, мм}} = 837.05$ Гр. сл. = V I Точн. = Н
	ОК-224 $F, \text{ см}^2 = 2.846$ $Q, \text{ кг} = 0.771$ $D_{\text{оп, мм}} = 82.5$ $P_{\text{н, мм}} = 295.5$ Гр. сл. = V Точн. = П		ОК-229 $F, \text{ см}^2 = 13.026$ $Q, \text{ кг} = 3.579$ $D_{\text{оп, мм}} = 183.07$ $P_{\text{н, мм}} = 475.4$ Гр. сл. = V Точн. = Н
	ОК-225 $F, \text{ см}^2 = 1.954$ $Q, \text{ кг} = 0.53$ $D_{\text{оп, мм}} = 40$ $P_{\text{н, мм}} = 137.5$ Гр. сл. = V Точн. = Н		ОК-230 $F, \text{ см}^2 = 2.135$ $Q, \text{ кг} = 0.578$ $D_{\text{оп, мм}} = 39.8$ $P_{\text{н, мм}} = 157.8$ Гр. сл. = V Точн. = Н











	ПК-231		ПК-236
	$F, \text{ см}^2 = 4.5$ $Q, \text{ кг} = 1.22$ $D_{\text{оп, мм}} = 50.8$ $P_{\text{н, мм}} = 118$ $\Gamma_{\text{р. сл.}} = \text{II}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 28.0$ $Q, \text{ кг} = 7.588$ $D_{\text{оп, мм}} = 87.3$ $P_{\text{н, мм}} = 230$ $\Gamma_{\text{р. сл.}} = \text{II}$ $\text{Точн.} = \text{H}$
	ПК-232		ПК-237
	$F, \text{ см}^2 = 3.85$ $Q, \text{ кг} = 1.043$ $D_{\text{оп, мм}} = 55.4$ $P_{\text{н, мм}} = 124$ $\Gamma_{\text{р. сл.}} = \text{II}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 2.332$ $Q, \text{ кг} = 0.632$ $D_{\text{оп, мм}} = 73.2$ $P_{\text{н, мм}} = 231.3$ $\Gamma_{\text{р. сл.}} = \text{V}$ $\text{Точн.} = \square \text{с.}$
	ПК-233		ПК-238
	$F, \text{ см}^2 = 2.642$ $Q, \text{ кг} = 0.716$ $D_{\text{оп, мм}} = 58.03$ $P_{\text{н, мм}} = 197$ $\Gamma_{\text{р. сл.}} = \text{V}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 4.95$ $Q, \text{ кг} = 1.341$ $D_{\text{оп, мм}} = 55.7$ $P_{\text{н, мм}} = 128$ $\Gamma_{\text{р. сл.}} = \text{II}$ $\text{Точн.} = \text{H}$
	ПК-234		ПК-239
	$F, \text{ см}^2 = 2.142$ $Q, \text{ кг} = 0.58$ $D_{\text{оп, мм}} = 46.04$ $P_{\text{н, мм}} = 153.8$ $\Gamma_{\text{р. сл.}} = \text{V}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 7.275$ $Q, \text{ кг} = 1.972$ $D_{\text{оп, мм}} = 171.2$ $P_{\text{н, мм}} = 633.7$ $\Gamma_{\text{р. сл.}} = \text{Ос.}$ $\text{Точн.} = \text{H}$
	ПК-235		ПК-240
	$F, \text{ см}^2 = 4.75$ $Q, \text{ кг} = 1.287$ $D_{\text{оп, мм}} = 66.1$ $P_{\text{н, мм}} = 271.7$ $\Gamma_{\text{р. сл.}} = \text{VII}$ $\text{Точн.} = \Pi$		$F, \text{ см}^2 = 4.073$ $Q, \text{ кг} = 1.104$ $D_{\text{оп, мм}} = 50.7$ $P_{\text{н, мм}} = 195$ $\Gamma_{\text{р. сл.}} = \text{VII}$ $\text{Точн.} = \Pi$










	<p>OK-241</p>		<p>OK-246</p>
	<p> $F, \text{ см}^2 = 1.996$ $Q, \text{ кг} = 0.541$ $D_{\text{оп, мм}} = 28.1$ $P_{\text{н, мм}} = 140$ $\Gamma_{\text{р. сл.}} = \vee \text{ II}$ $\text{Точн.} = \Pi$ </p>		<p> $F, \text{ см}^2 = 0.94$ $Q, \text{ кг} = 0.256$ $D_{\text{оп, мм}} = 22.1$ $P_{\text{н, мм}} = 96$ $\Gamma_{\text{р. сл.}} = \vee$ $\text{Точн.} = \Pi$ </p>
	<p>OK-242</p>		<p>OK-247</p>
	<p> $F, \text{ см}^2 = 0.8186$ $Q, \text{ кг} = 0.222$ $D_{\text{оп, мм}} = 30.9$ $P_{\text{н, мм}} = 107.4$ $\Gamma_{\text{р. сл.}} = \vee$ $\text{Точн.} = \text{H}$ </p>		<p> $F, \text{ см}^2 = 9.624$ $Q, \text{ кг} = 2.608$ $D_{\text{оп, мм}} = 186.7$ $P_{\text{н, мм}} = 503.2$ $\Gamma_{\text{р. сл.}} = \vee \text{ I}$ $\text{Точн.} = \Pi$ </p>
	<p>OK-243</p>		<p>OK-248</p>
	<p> $F, \text{ см}^2 = 0.811$ $Q, \text{ кг} = 0.22$ $D_{\text{оп, мм}} = 30.9$ $P_{\text{н, мм}} = 104.8$ $\Gamma_{\text{р. сл.}} = \vee$ $\text{Точн.} = \text{H}$ </p>		<p> $F, \text{ см}^2 = 27.41$ $Q, \text{ кг} = 7.428$ $D_{\text{оп, мм}} = 140$ $P_{\text{н, мм}} = 1184$ $\Gamma_{\text{р. сл.}} = \text{O c.}$ $\text{Точн.} = \text{H}$ </p>
	<p>OK-244</p>		<p>OK-249</p>
	<p> $F, \text{ см}^2 = 1.76$ $Q, \text{ кг} = 0.477$ $D_{\text{оп, мм}} = 35.2$ $P_{\text{н, мм}} = 116.7$ $\Gamma_{\text{р. сл.}} = \vee \text{ II}$ $\text{Точн.} = \Pi$ </p>		<p> $F, \text{ см}^2 = 3.967$ $Q, \text{ кг} = 1.075$ $D_{\text{оп, мм}} = 126$ $P_{\text{н, мм}} = 331.3$ $\Gamma_{\text{р. сл.}} = \text{O c.}$ $\text{Точн.} = \text{H}$ </p>
	<p>OK-245</p>		<p>OK-250</p>
	<p> $F, \text{ см}^2 = 8.336$ $Q, \text{ кг} = 2.26$ $D_{\text{оп, мм}} = 158$ $P_{\text{н, мм}} = 436$ $\Gamma_{\text{р. сл.}} = \vee$ $\text{Точн.} = \text{H}$ </p>		<p> $F, \text{ см}^2 = 116.2$ $Q, \text{ кг} = 31.49$ $D_{\text{оп, мм}} = 183.7$ $P_{\text{н, мм}} = 308.8$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{H}$ </p>











	OK-251		OK-256
	$F, \text{см}^2 = 2.27$ $Q, \text{кг} = 0.615$ $D_{\text{оп,мм}} = 44$ $P_{\text{н,мм}} = 249$ $\Gamma_{\text{р. сл.}} = \text{OC}$ $\text{Точн.} = \text{H}$		$F, \text{см}^2 = 3.258$ $Q, \text{кг} = 0.883$ $D_{\text{оп,мм}} = 90$ $P_{\text{н,мм}} = 386.1$ $\Gamma_{\text{р. сл.}} = \text{V}$ $\text{Точн.} = \text{П}$
	OK-252		OK-257
	$F, \text{см}^2 = 0.5$ $Q, \text{кг} = 0.136$ $D_{\text{оп,мм}} = 11.7$ $P_{\text{н,мм}} = 74$ $\Gamma_{\text{р. сл.}} = \text{IV}$ $\text{Точн.} = \text{H}$		$F, \text{см}^2 = 3.095$ $Q, \text{кг} = 1.058$ $D_{\text{оп,мм}} = 82$ $P_{\text{н,мм}} = 456.8$ $\Gamma_{\text{р. сл.}} = \text{V}$ $\text{Точн.} = \text{П}$
	OK-253		OK-258
	$F, \text{см}^2 = 2.393$ $Q, \text{кг} = 0.649$ $D_{\text{оп,мм}} = 44.6$ $P_{\text{н,мм}} = 167.5$ $\Gamma_{\text{р. сл.}} = \text{V}$ $\text{Точн.} = \text{H}$		$F, \text{см}^2 = 2.186$ $Q, \text{кг} = 0.592$ $D_{\text{оп,мм}} = 41.7$ $P_{\text{н,мм}} = 162.3$ $\Gamma_{\text{р. сл.}} = \text{V}$ $\text{Точн.} = \text{H}$
	OK-254		OK-259
	$F, \text{см}^2 = 1.45$ $Q, \text{кг} = 0.393$ $D_{\text{оп,мм}} = 53.1$ $P_{\text{н,мм}} = 178$ $\Gamma_{\text{р. сл.}} = \text{IV}$ $\text{Точн.} = \text{H}$		$F, \text{см}^2 = 12.145$ $Q, \text{кг} = 3.291$ $D_{\text{оп,мм}} = 115.2$ $P_{\text{н,мм}} = 539$ $\Gamma_{\text{р. сл.}} = \text{V}$ $\text{Точн.} = \text{H}$
	OK-255		OK-260
	$F, \text{см}^2 = 1.37$ $Q, \text{кг} = 0.377$ $D_{\text{оп,мм}} = 52.5$ $P_{\text{н,мм}} = 170$ $\Gamma_{\text{р. сл.}} = \text{IV}$ $\text{Точн.} = \text{H}$		$F, \text{см}^2 = 2.317$ $Q, \text{кг} = 0.629$ $D_{\text{оп,мм}} = 53.9$ $P_{\text{н,мм}} = 232.2$ $\Gamma_{\text{р. сл.}} = \text{V}$ $\text{Точн.} = \text{H}$









	<p>ОК-261</p> <p> $F, \text{см}^2 = 13.663$ $Q, \text{кг} = 3.703$ $D_{\text{оп,мм}} = 103.6$ $P_{\text{н,мм}} = 1021.8$ $\Gamma_{\text{р. сл.}} = \vee \text{I}$ $\text{Точн.} = \text{H}$ </p>		<p>ОК-266</p> <p> $F, \text{см}^2 = 2.247$ $Q, \text{кг} = 0.607$ $D_{\text{оп,мм}} = 34$ $P_{\text{н,мм}} = 155.7$ $\Gamma_{\text{р. сл.}} = \vee$ $\text{Точн.} = \text{П}$ </p>
	<p>ОК-262</p> <p> $F, \text{см}^2 = 2.17$ $Q, \text{кг} = 0.588$ $D_{\text{оп,мм}} = 51.7$ $P_{\text{н,мм}} = 149$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{H}$ </p>		<p>ОК-267</p> <p> $F, \text{см}^2 = 2.247$ $Q, \text{кг} = 0.609$ $D_{\text{оп,мм}} = 35$ $P_{\text{н,мм}} = 166.6$ $\Gamma_{\text{р. сл.}} = \text{O.C.}$ $\text{Точн.} = \text{П}$ </p>
	<p>ОК-263</p> <p> $F, \text{см}^2 = 9.132$ $Q, \text{кг} = 2.475$ $D_{\text{оп,мм}} = 161$ $P_{\text{н,мм}} = 531.9$ $\Gamma_{\text{р. сл.}} = \vee \text{I}$ $\text{Точн.} = \text{П}$ </p>		<p>ОК-268</p> <p> $F, \text{см}^2 = 2.145$ $Q, \text{кг} = 0.581$ $D_{\text{оп,мм}} = 36$ $P_{\text{н,мм}} = 116.8$ $\Gamma_{\text{р. сл.}} = \vee$ $\text{Точн.} = \text{П}$ </p>
	<p>ОК-264</p> <p> $F, \text{см}^2 = 4.931$ $Q, \text{кг} = 1.336$ $D_{\text{оп,мм}} = 85$ $P_{\text{н,мм}} = 301.4$ $\Gamma_{\text{р. сл.}} = \vee$ $\text{Точн.} = \text{H}$ </p>		<p>ОК-269</p> <p> $F, \text{см}^2 = 1.914$ $Q, \text{кг} = 0.519$ $D_{\text{оп,мм}} = 58.4$ $P_{\text{н,мм}} = 187.1$ $\Gamma_{\text{р. сл.}} = \text{I} \vee$ $\text{Точн.} = \text{H}$ </p>
	<p>ОК-265</p> <p> $F, \text{см}^2 = 1.928$ $Q, \text{кг} = 0.523$ $D_{\text{оп,мм}} = 79.4$ $P_{\text{н,мм}} = 245.2$ $\Gamma_{\text{р. сл.}} = \vee$ $\text{Точн.} = \text{H}$ </p>		<p>ОК-270</p> <p> $F, \text{см}^2 = 2.356$ $Q, \text{кг} = 0.639$ $D_{\text{оп,мм}} = 81.6$ $P_{\text{н,мм}} = 260.7$ $\Gamma_{\text{р. сл.}} = \text{I} \vee$ $\text{Точн.} = \text{H}$ </p>

	OK-271		OK-276
	$F, \text{ см}^2 = 1.138$ $Q, \text{ кг} = 0.308$ $D_{\text{оп, мм}} = 33$ $P_{\text{н, мм}} = 86.7$ $\Gamma_{\text{р, сл.}} = I \vee$ $\text{Точн.} = \Pi$		$F, \text{ см}^2 = 4.997$ $Q, \text{ кг} = 1.354$ $D_{\text{оп, мм}} = 152.1$ $P_{\text{н, мм}} = 501.6$ $\Gamma_{\text{р, сл.}} = V$ $\text{Точн.} = H$
	OK-272		OK-277
	$F, \text{ см}^2 = 1.926$ $Q, \text{ кг} = 0.522$ $D_{\text{оп, мм}} = 41.2$ $P_{\text{н, мм}} = 127.4$ $\Gamma_{\text{р, сл.}} = I \vee$ $\text{Точн.} = \Pi$		$F, \text{ см}^2 = 10.516$ $Q, \text{ кг} = 2.85$ $D_{\text{оп, мм}} = 141.2$ $P_{\text{н, мм}} = 505.5$ $\Gamma_{\text{р, сл.}} = V$ $\text{Точн.} = H$
	OK-273		OK-278
	$F, \text{ см}^2 = 4.36$ $Q, \text{ кг} = 1.182$ $D_{\text{оп, мм}} = 64.8$ $P_{\text{н, мм}} = 225$ $\Gamma_{\text{р, сл.}} = V$ $\text{Точн.} = \Pi$		$F, \text{ см}^2 = 4.036$ $Q, \text{ кг} = 1.094$ $D_{\text{оп, мм}} = 130.4$ $P_{\text{н, мм}} = 437.12$ $\Gamma_{\text{р, сл.}} = I \vee$ $\text{Точн.} = \Pi$
	OK-274		OK-279
	$F, \text{ см}^2 = 2.41$ $Q, \text{ кг} = 0.653$ $D_{\text{оп, мм}} = 60$ $P_{\text{н, мм}} = 195.7$ $\Gamma_{\text{р, сл.}} = I \vee$ $\text{Точн.} = \Pi$		$F, \text{ см}^2 = 0.797$ $Q, \text{ кг} = 0.216$ $D_{\text{оп, мм}} = 21.4$ $P_{\text{н, мм}} = 81.6$ $\Gamma_{\text{р, сл.}} = V$ $\text{Точн.} = H$
	OK-275		OK-280
	$F, \text{ см}^2 =$ $Q, \text{ кг} =$ $D_{\text{оп, мм}} =$ $P_{\text{н, мм}} =$ $\Gamma_{\text{р, сл.}} = I \vee$ $\text{Точн.} = \Pi$		$F, \text{ см}^2 = 0.816$ $Q, \text{ кг} = 0.221$ $D_{\text{оп, мм}} = 33.6$ $P_{\text{н, мм}} = 110$ $\Gamma_{\text{р, сл.}} = V I$ $\text{Точн.} = \Pi$

	ПК-281		ПК-286
	$F, \text{см}^2 = 1.160$ $Q, \text{кг} = 0.314$ $D_{\text{оп,мм}} = 42.4$ $P_{\text{н,мм}} = 120$ $\Gamma_{\text{р. сл.}} = \text{II}$ $\text{Точн.} = \Pi$		$F, \text{см}^2 =$ $Q, \text{кг} =$ $D_{\text{оп,мм}} =$ $P_{\text{н,мм}} =$ $\Gamma_{\text{р. сл.}} = \text{IV}$ $\text{Точн.} = \Pi$
	ПК-282		ПК-287
	$F, \text{см}^2 = 1.383$ $Q, \text{кг} = 0.375$ $D_{\text{оп,мм}} = 42$ $P_{\text{н,мм}} = 139$ $\Gamma_{\text{р. сл.}} = \text{II}$ $\text{Точн.} = \Pi$		$F, \text{см}^2 = 3.48$ $Q, \text{кг} = 0.943$ $D_{\text{оп,мм}} = 59$ $P_{\text{н,мм}} = 150$ $\Gamma_{\text{р. сл.}} = \text{IV}$ $\text{Точн.} = \Pi$
	ПК-283		ПК-288
	$F, \text{см}^2 = 0.56$ $Q, \text{кг} = 0.152$ $D_{\text{оп,мм}} = 19.3$ $P_{\text{н,мм}} = 77$ $\Gamma_{\text{р. сл.}} = \text{VI}$ $\text{Точн.} = \Pi$		$F, \text{см}^2 = 0.56$ $Q, \text{кг} = 0.152$ $D_{\text{оп,мм}} = 18.5$ $P_{\text{н,мм}} = 56$ $\Gamma_{\text{р. сл.}} = \text{IV}$ $\text{Точн.} = \Pi$
	ПК-284		ПК-289
	$F, \text{см}^2 = 10.838$ $Q, \text{кг} = 2.937$ $D_{\text{оп,мм}} = 123$ $P_{\text{н,мм}} = 577.4$ $\Gamma_{\text{р. сл.}} = \text{IV}$ $\text{Точн.} = \Pi$		$F, \text{см}^2 = 0.523$ $Q, \text{кг} = 0.142$ $D_{\text{оп,мм}} = 23.3$ $P_{\text{н,мм}} = 53.9$ $\Gamma_{\text{р. сл.}} = \text{IV}$ $\text{Точн.} = \Pi$
	ПК-285		ПК-290
	$F, \text{см}^2 = 5.26$ $Q, \text{кг} = 1.425$ $D_{\text{оп,мм}} = 64.8$ $P_{\text{н,мм}} = 206$ $\Gamma_{\text{р. сл.}} = \text{IV}$ $\text{Точн.} = \Pi$		$F, \text{см}^2 = 2.8$ $Q, \text{кг} = 0.759$ $D_{\text{оп,мм}} = 53$ $P_{\text{н,мм}} = 180.7$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \Pi$

	OK-291		OK-296
	$F, \text{ см}^2 = 1,14$ $Q, \text{ кг} = 0,309$ $D_{\text{оп, мм}} = 26,3$ $P_{\text{н, мм}} = 62$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \Pi$		$F, \text{ см}^2 = 8,995$ $Q, \text{ кг} = 2,438$ $D_{\text{оп, мм}} = 180$ $P_{\text{н, мм}} = 497,3$ $\Gamma_{\text{р. сл.}} = \vee$ $\text{Точн.} = \Pi$
	OK-292		OK-297
	$F, \text{ см}^2 = 1,08$ $Q, \text{ кг} = 0,293$ $D_{\text{оп, мм}} = 54$ $P_{\text{н, мм}} = 112$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \Pi$		$F, \text{ см}^2 = 10,37$ $Q, \text{ кг} = 2,81$ $D_{\text{оп, мм}} = 170,1$ $P_{\text{н, мм}} = 667,3$ $\Gamma_{\text{р. сл.}} = \vee \text{I}$ $\text{Точн.} = \text{H}$
	OK-293		OK-298
	$F, \text{ см}^2 =$ $Q, \text{ кг} =$ $D_{\text{оп, мм}} =$ $P_{\text{н, мм}} =$ $\Gamma_{\text{р. сл.}} = \text{IV}$ $\text{Точн.} = \Pi$		$F, \text{ см}^2 = 44,309$ $Q, \text{ кг} = 12,008$ $D_{\text{оп, мм}} = 177,2$ $P_{\text{н, мм}} = 1656$ $\Gamma_{\text{р. сл.}} = \text{O} \subset$ $\text{Точн.} = \Pi$
	OK-294		OK-299
	$F, \text{ см}^2 = 27,07$ $Q, \text{ кг} = 7,336$ $D_{\text{оп, мм}} = 178$ $P_{\text{н, мм}} = 689,9$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{O} \subset$		$F, \text{ см}^2 = 31,429$ $Q, \text{ кг} = 8,517$ $D_{\text{оп, мм}} = 201$ $P_{\text{н, мм}} = 1589$ $\Gamma_{\text{р. сл.}} = \square \subset$ $\text{Точн.} = \Pi$
	OK-295		OK-300
	$F, \text{ см}^2 = 4,866$ $Q, \text{ кг} = 1,319$ $D_{\text{оп, мм}} = 129$ $P_{\text{н, мм}} = 405,2$ $\Gamma_{\text{р. сл.}} = \vee \text{I}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 2,75$ $Q, \text{ кг} = 0,745$ $D_{\text{оп, мм}} = 55,2$ $P_{\text{н, мм}} = 120$ $\Gamma_{\text{р. сл.}} = \text{II}$ $\text{Точн.} = \text{H}$

	□К-301		□К-306
	$F, \text{ см}^2 = 2,75$ $Q, \text{ кг} = 0,745$ $D_{\text{оп, мм}} = 50,3$ $P_{\text{н, мм}} = 111$ $\Gamma_{\text{р, сл.}} = \text{II}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 4,75$ $Q, \text{ кг} = 1,287$ $D_{\text{оп, мм}} = 50,9$ $P_{\text{н, мм}} = 119$ $\Gamma_{\text{р, сл.}} = \text{II}$ $\text{Точн.} = \text{H}$
	□К-302		□К-307
	$F, \text{ см}^2 = 3,25$ $Q, \text{ кг} = 0,881$ $D_{\text{оп, мм}} = 50,4$ $P_{\text{н, мм}} = 113$ $\Gamma_{\text{р, сл.}} = \text{II}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 5,0$ $Q, \text{ кг} = 1,355$ $D_{\text{оп, мм}} = 100,1$ $P_{\text{н, мм}} = 210$ $\Gamma_{\text{р, сл.}} = \text{II}$ $\text{Точн.} = \text{H}$
	□К-303		□К-308
	$F, \text{ см}^2 = 3,75$ $Q, \text{ кг} = 1,016$ $D_{\text{оп, мм}} = 50,6$ $P_{\text{н, мм}} = 115$ $\Gamma_{\text{р, сл.}} = \text{II}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 5,5$ $Q, \text{ кг} = 1,491$ $D_{\text{оп, мм}} = 100,1$ $P_{\text{н, мм}} = 211$ $\Gamma_{\text{р, сл.}} = \text{II}$ $\text{Точн.} = \text{H}$
	□К-304		□К-309
	$F, \text{ см}^2 = 4,0$ $Q, \text{ кг} = 1,084$ $D_{\text{оп, мм}} = 50,6$ $P_{\text{н, мм}} = 116$ $\Gamma_{\text{р, сл.}} = \text{II}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 6,0$ $Q, \text{ кг} = 1,626$ $D_{\text{оп, мм}} = 100,2$ $P_{\text{н, мм}} = 212$ $\Gamma_{\text{р, сл.}} = \text{II}$ $\text{Точн.} = \text{H}$
	□К-305		□К-310
	$F, \text{ см}^2 = 4,25$ $Q, \text{ кг} = 1,152$ $D_{\text{оп, мм}} = 50,7$ $P_{\text{н, мм}} = 117$ $\Gamma_{\text{р, сл.}} = \text{II}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 6,5$ $Q, \text{ кг} = 1,762$ $D_{\text{оп, мм}} = 100,2$ $P_{\text{н, мм}} = 213$ $\Gamma_{\text{р, сл.}} = \text{II}$ $\text{Точн.} = \text{H}$

	□К-311		□К-316
	$F, \text{ см}^2 = 7.5$ $Q, \text{ кг} = 2.033$ $D_{\text{оп, мм}} = 100.3$ $P_{\text{н, мм}} = 215$ $\Gamma_{\text{р. сл.}} = \text{II}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 2.57$ $Q, \text{ кг} = 0.696$ $D_{\text{оп, мм}} = 45$ $P_{\text{н, мм}} = 139$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{П}$
	□К-312		□К-317
	$F, \text{ см}^2 = 8.5$ $Q, \text{ кг} = 2.304$ $D_{\text{оп, мм}} = 100.4$ $P_{\text{н, мм}} = 217$ $\Gamma_{\text{р. сл.}} = \text{II}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 9.839$ $Q, \text{ кг} = 2.66$ $D_{\text{оп, мм}} = 119$ $P_{\text{н, мм}} = 585.8$ $\Gamma_{\text{р. сл.}} = \text{VI}$ $\text{Точн.} = \text{П}$
	□К-313		□К-318
	$F, \text{ см}^2 = 9.5$ $Q, \text{ кг} = 2.575$ $D_{\text{оп, мм}} = 100.5$ $P_{\text{н, мм}} = 219$ $\Gamma_{\text{р. сл.}} = \text{II}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 3.549$ $Q, \text{ кг} = 0.961$ $D_{\text{оп, мм}} = 140.8$ $P_{\text{н, мм}} = 355$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{H}$
	□К-314		□К-319
	$F, \text{ см}^2 =$ $Q, \text{ кг} =$ $D_{\text{оп, мм}} =$ $P_{\text{н, мм}} =$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{OC}$		$F, \text{ см}^2 = 4.565$ $Q, \text{ кг} = 1.237$ $D_{\text{оп, мм}} = 62$ $P_{\text{н, мм}} = 132.4$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{H}$
	□К-315		□К-320
	$F, \text{ см}^2 =$ $Q, \text{ кг} =$ $D_{\text{оп, мм}} =$ $P_{\text{н, мм}} =$ $\Gamma_{\text{р. сл.}} = \text{VI}$ $\text{Точн.} = \text{H}$		$F, \text{ см}^2 = 6.635$ $Q, \text{ кг} = 1.798$ $D_{\text{оп, мм}} = 60$ $P_{\text{н, мм}} = 137.1$ $\Gamma_{\text{р. сл.}} = \text{III}$ $\text{Точн.} = \text{H}$